STATE OF NEW MEXICO ERGY AND MINERALS DEPARTMENT

" we. or corics acceives	
DISTRIBUTION	
SANTA PE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

DISTRIBUTION		P. O. BOX 2088			Form C-103
SANTA PE		SANTA FE, NEW MEXICO 87501			Revised 10-1-78
FILE		SANIA FE, NEW	WEXICO 67301	5a. Indicate Typ	no of Legra
U.S.O.S.			•	State State	Foo X
LAND OFFICE			•	5. State Oil & G	
ROTARSO				3, State Off & G	Lease IV.
				mmm	mmmn
SUNDRY NOTICES AND REPORTS ON WELLS			. (1111111)		
1	USE "APPLICATION FOR PERM	T -" (FORM C-101) FOR SUC	H PROPOSALS.)	7. Unit Agreeme	ent Name
OIL	NELL OTHER-	Re-entry			
2. Name of Operator		110 01111		8. Farm or Leas	se Name
H. B. Rhoads	. Inc.			Wallace	:
3. Address of Operator	,			9. Well No.	
	32, Midland, Texas	79704		4	
4. Location of Well				10. Field and P	
	1980	North	LINE AND660	Gladiol	a Wolfcamp
UNIT LETTER		ET FROM THE	LINE AND		
Fast	4	125	RANGE38E	()	
THE	LINE, SECTION	TOWNSHIP			
THITTINITY:	1. (11111111111111111111111111111111111	5. Elevation (Show whether	DF, RT, GR, etc.)	12. County	
		3873' Œ _		Lea	_//////////////////////////////////////
16.	Check Appropriat	e Box To Indicate N	lature of Notice, Repo	rt or Other Data	
NO	TICE OF INTENTION		subs	EQUENT REPORT OF	F:
PERFORM REMEDIAL WORL		PLUG AND ABANDON	REMEDIAL WORK		ERING CASING
TEMPORARILY ABANDON			COMMENCE DRILLING OPHS.	PLUG	AND ABANDONMENT
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT JOI	• 📙	
			OTHER		
OTHER					
·	- Co-plated Operations (CI	early state all pertinent det	lails, and give pertinent dates,	, including estimated date of	of starting any propose
work) SEE RULE 1	fos.	eurry state un periment der		· .	
10/27/9/ 10	adad bala with 13	bbls 10 lb /ggl	. brine water. Se	t cement nlug = 2	S sv Cl H
	ment at 9114-8889		. Dille water. Se	. carem prog z	.5 JA, CI. 11
			9244'; loaded hole	with 115 bbl. 10)#/aal. mud
fr.	om 9115-4200': se	et 25 sx Cl. H ce	ment plug fram 591	1-5686'	, 9=
	t 5-1/ 2 " casing a				
10/30/86 - Spe	otted 30 sx. Cl. H	Hicement w/2% CoC	l ₂ at 4257'. Displ	laced hole with 2	45 bbl.
I O _i	⅓/gal.mud; set 4	40 sx Cl. H cermen	it plug at 4257'		
10/31/86 - Wei	nt in hole with t	ubing and tagged	top of cement at 4	125'. Set 30 sx	Cl. H
cer	ment plug from 22	14-2129'			
. Se	t 10 sx Cl. H cem	ent plug at surta	ice and set dry hol	e marker	L . 2 00 DV
Cl	eaned up location	, rigged down uni	t and cut off anch	ors. Unit releas	sea ar 3:00 HM
			•		
		•			

18. 1 hereby certify the	at the information above is true and comple	te to the best of my knowledge and belief.	11///0/
BISHED .	/ LUU UJ	Agent Agent	DATE 11/0/00
C_{i}	(1)	OIL & GAS INSPECTOR	MAY 1 4 1987