

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-101
Effective 1-1-65

| | |
|--------------------------------|---|
| 5a. Indicate Type of Lease | |
| State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No. | |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Skelton Oil Company | 8. Farm or Lease Name Newmont |
| 3. Address of Operator P.O. Box 176 Hobbs, New Mexico 88240 | 9. Well No. # M 1 |
| 4. Location of Well UNIT LETTER K, 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 7 TOWNSHIP 12S RANGE 38E NMPM. | 10. Field and Pool, or Wildcat Gladiola Devonian |
| 15. Elevation (Show whether DF, RT, CR, etc.) | 12. County Lea |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|--|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

No production in 1985

We intend to plug and abandon well.

1. Set CIBP & cap w/35' cement @ 11,400'.
2. Set 100' cement plug @ top of Abo, 7000'.
3. Pull 4400' \pm 5 1/2" casing. Set 100' cement plug 50/50 in & out of stub to cover 2 1/2" Shoe.
4. Set 100' plug @ top of Salt, 2100 \pm .
5. Set 10 sack plug @ surface. Load hole w/10# Salt Gel. Set Marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

| | | |
|---|----------------------|-------------------------|
| SIGNED <u>George A. Harker</u> | TITLE <u>Manager</u> | DATE <u>8-5-85</u> |
| ORIGINAL SIGNED BY <u>JERRY SEXTON</u> DISTRICT SUPERVISOR | | |
| APPROVED BY <u>J. J.</u> | TITLE <u></u> | DATE <u>SEP 26 1985</u> |
| CONDITIONS OF APPROVAL, IF ANY: | | |

RECEIVED

SEP 25 1985

OFFICE
HOBBS CRANCE