NO. OF COPIES RECEIVED DISTRIBUTION		Form C-103 Supersedes Old C-102 and C-103			
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION Effective 1-1-65				
FILE			5a. Indicate Typ	a of Lease	
U.S.G.S.			State	Fee X	
LAND OFFICE			5. State Oil & G		
OPERATOR			3, 3,2,3 3,1 4 3	20 2000 (10)	
SUNDRY NOTICES AND REPORTS ON WELLS "Go not use this form for proposals to drill or to deepen or plug back to a different reservoir. "Use "happlication for permit -" (FORM C-101) FOR SUCH PROPOSALS.)					
OIL X WELL OTHER-				nt Name	
2. Name of 1; erator				8. Farm or Lease Name	
SKLLTON OIL COMPANY			Jones s		
3. Address of Sperator D. O. BOX 840 HOBBS, NE HEXILO 88240				9. Well No. Úne	
4. Location of Well				13. Field and Pool, or Wildcat Cladiola - Wolfcamp	
UNIT SETTER J , 1980 FEET FROM THE East LINE AND 1980 FEET FROM				- worlcach	
THE SOUTH LINE, SE	ection 7 township 1.2	TO RANGE SOFE NMPI			
15. Elevation (Show whether DF, RT, GR, etc.)			12. County	<i>.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</i>	
			Lea		
16. Chec	ck Appropriate Box To Indicate N	lature of Notice Report of O	ther Data		
	FINTENTION TO:		NT REPORT OF	:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTE	RING CASING	
TEMPORAR!LY ABANDON	_	COMMENCE DRILLING OPNS.	PLUG	AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB			
	<u></u>	OTHER			
OTHER					
17. Describe Proposed or Complete work) SEE RULE 1103.	d Operations (Clearly state all pertinent det	ails, and give pertinent dates, includi	ng estimated date o	starting any proposed	
Set 25sacks lug at 9400 feet above enforations					
Set 50sacks plug i	n and out of stub at 5700	feet.			
Set 25 sac ks plug a	t 4,400 feet in 8 5/6				
Set 25 sacks plug at surface.					

18. I hereby certify that the inform	ation above is true and complete to the best	of my knowledge and belief.			
SIGNED	retter TITLE	Tresident	DATE	8/20/73	
	<u> </u>				

APPROVED BY