NEW MEXICO OIL CONSERVATION COMMISSION    SANT A FE		<del></del>	_					
SANTA FE    SUBJECT   Subj	NO. OF COPIES RECE	IVED	_				_	
NEW MEXICO OIL CONSERVATION COMMISSION  Filter   1,4-65	DISTRIBUTION	4	_				. *	-
U.S.G.S.   LAND OFFICE   SOLIDORY NOTICES AND REPORTS ON WELLS   Solidor of the processes of politic of the processes of the politic of the processes of the pr	SANTAFE		NE	MEXICO OIL CON	SERVATION COMMI	SSION 👙		
State OPERATOR  SUNDRY NOTICES AND REPORTS ON WELLS  (OC NOT USE THIS FORM FOR MERCHAND OF TEXAS  AMERICAN PETROFINA COMPANY OF TEXAS  Address of Operator  Box 1311, Rig Spring, Texas 79720  4, Location of Well  ONLY LETTER  H  2316.6  FEET FROM THE  BOX 1311, Rig Spring, Texas 79720  10. Field and Pool, or Wildert  THE SOUTH  THE SOUTH  THE SOUTH  LINE, SECTION  TOMMANIP 12-8  ALEGE OF INTENTION TO:  PREVENT ALBERT OF INTENTION TO:  PREVENT ALBERT OF STATES  CHARGE OF INTENTION TO:  PREVENT ALBERT OF STATES  SUBSEQUENT REPORT OF:  PREVENT ALBERT OF STATES OF	FILE					!		
S. State Oil & Gos Lease No.    South   Support   Suppor	U.S.G.S.						5a. Indicate Ty	
SUNDRY NOTICES AND REPORTS ON WELLS  OF THE PROPERTY OF THE PR	LAND OFFICE						State	Fee 🕱
AMERICAN PETROPINA COMPANY OF TEXAS  Box 1311, Big Spring, Texas 79720  S. Form or Lesue Name  Newmont Oil Company  9, Well No.  10, Fleid and Pool, or Wildord  Cladicle Devonten  The South  Th	OPERATOR						5. State Oil & C	Gas Lease No.
AMERICAN PETROPINA COMPANY OF TEXAS  Box 1311, Big Spring, Texas 79720  10. Fleid and Fool, or Wildord  Cladicle Devonien  The South Cive, section 7 township 12-S sance 38-E NAME.  15. Elevation (Show whether DF, RT, CR, etc.)  3882 DF  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK COMPANIALY ABANDON CHANGE PLANS CHANGE PLANS COMMENCE DRILLING OPEN.  TEMPORALITY ABANDON PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propositions, SEE RULE 1768.  8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot  36 Sx plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 Sx plug in and out of 5½ casing Spotted 15 Sx plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600			—					
AMERICAN PETROFINA COMPANY OF TEXAS  ANABISCAN PETROFINA COMPANY OF TEXAS  AMERICAN PETROFINA COMPANY OF TEXAS  ANABISCAN PETROFINA COMPANY OF TEXAS  Box 1311, Big Spring, Texas 79720  10. Flaid and Fool, or Wildows  Cladicals Devonian  THE South	(DO NOT HEE I	SUNE	RY NOTICES	AND REPORTS ON	WELLS			
AMERICAN PETROFINA COMPANY OF TEXAS  ANABERICAN PETROFINA COMPANY OF TEXAS  Address of Operator  Box 1311, Big Spring, Texas 79720  4. Location of Well  UNIT LETTER N . 2316.6 FEET FROM THE West LINE AND 330 FEET FROM  TOWNSHIP 12-S RANGE 38-E NAPPH.  15. Elevation (Show whether DF, RT, CR, etc.)  16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK TEMPORABILY ABANDON PULL ON ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE BULLE 103.  8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot 36 Sx plug @ 10,943 to 11,233. Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 Sx plug in and out of 5½ casing stub @ 5952. Spotted 25 Sx plug in and out of base of 8 5/8" casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface.  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600		USE "APPLIC	ATION FOR PERMIT -	" (FORM C-101) FOR SU	CH PROPOSALS.)	SERVOIR.		
AMERICAN PETROFINA COMPANY OF TEXAS  AMERICAN PETROFINA COMPANY OF TEXAS  AMERICAN PETROFINA COMPANY OF TEXAS  3. Address of Operator  Box 1311, \$ig Spring, Texas 79720  4. Location of Well  UNIT LETTER N 2316.6 PEET FROM THE West LINE AND 330 PEET FROM  THE South LINE, SECTION 7 TOWNSHIP 12-8 RANGE 38-E NUMPH.  15. Elevation (Show whether DF, RT, CR, etc.)  16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK ALTERIAS CASING  TEMPORALITY ABANDON CHARGE PLANS  REMEDIAL WORK  ALTERING CASING  PLUG AND ABANDONMENT PLUG AND ABAND							7. Unit Agreem	ent Name
AMERICAN PETROFINA COMPANY OF TEXAS  3. Address of Operator  Box 1311, Big Spring, Texas 79720  4. Location of Well  UNIT LETTER N 2316.6 FEET FROM THE West Line And 330 FEET FROM  The South Line, Section 7 Township 12-S Range 38-E NAME.  South Line, Section 7 Township 12-S Range 38-E NAME.  Check Appropriate Box To Indicate Nature of Notice, Report of Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK ALTER CASING  PULL OR ALTER CASING CHMENT JOS OTHER  OTHER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  OTHER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  OTHER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  OTHER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  OTHER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  OTHER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  OTHER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  CASING TEST AND CEMENT JOS OTHER  TO THER COMMENCE DRILLING DANS.  TO THER COMMENCE DRILLING DANS.  TO THER COMMENCE DRILLING DANS		WELL	OTHER-		· · · · · · · · · · · · · · · · · · ·		8. Form or Leg	se Name
3. Address of Operator  Box 1311, Big Spring, Texas 79720  4. Location of Well  Unit Letter N	•	AMERICAN	PETROFINA C	OMPANY OF TEXA	S			
Box 1311, Big Spring, Texas 79720  1. Location of Well  UNIT LETTER N 2316.6  FEET FROM THE West LINE AND 330  THE SOUTH LINE, SECTION 7 TOWNSHIP 12-8  AREAS 38-B NMPM.  15. Elevation (Show whether DF, RT, CR, etc.)  3882 DF Lea  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK COMMERCE DRILLING OPNS.  CHANGE PLANS CHANGE PLANS COMMERCE DRILLING OPNS.  CHANGE PLANS CHANGE TEST AND CEMENT JOB  OTHER  OTHER  36 Sx plug @ 10,943 to 11,233.  Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot  36 Sx plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 8x plug in and out of 5½ casing. Spotted 15 8x plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994  8 5/8 Surf - 4600							<del></del>	
A Location of Well  UNIT LETTER N 2316.6  THE South LINE, SECTION 7 TOWNSHIP 12-5  SOUTH LINE, SECTION 7 TOWNSHIP 12-5  SARE NAMEN.  15. Elevation (Show whether DF, RT, CR, etc.)  12. County  Lea  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK COMMERCE DRILLING OPNS.  CHANGE PLANS CHANGE DRILLING OPNS.  CHANGE PLANS OTHER  OTHER  OTHER  OTHER  38-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot  36 Sx plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 Sx plug in and out of 5½ casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600	•		Ric Enrine	Towns 70720	<b>\</b>			1
South Line, Section 7 Township 12-S NANDE 38-E NAME.  18. Elevation (Show whether DF, RT, CR, etc.)  18. Elevation (Show whether DF, RT, CR, etc.)  18. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  18. Elevation (Show whether DF, RT, CR, etc.)  19. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF:  19. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF:  19. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF:  10. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF:  11. Open The Report Of Check Appropriate Commence of Subsequent Commence of Subseque		DOX 1311,	are ohr rue	, 1eas ///20	,		10. Field and F	Pool, or Wildcat
13. Elevation (Show whether DF, RT, CR, etc.)  12. County  13882 DF  13. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PLUG AND ABANDON  PLUG AND ABANDON  CHANGE PLANS  OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE NULE 1 103.  8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10\$\frac{\pi}{\pi}\$ mud. Spot  36 \$x\$ plug @ 10,943 to 11,233.  Rigged up to work 5\$\frac{\pi}{\pi}\$ casing. Casing parted @ 5952. Spotted 25 \$x\$ plug in and out of \$\frac{\pi}{\pi}\$ casing stub @ 5952. Spotted 25 \$x\$ plug in and out of \$\frac{\pi}{\pi}\$ casing stub @ 5952. Spotted 25 \$x\$ plug in and out of base of 8 5/8" casing. Spotted 15 \$x\$ plug in top of 8 5/8" casing @ surface.  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5\frac{\pi}{\pi}\$ 5952 - 11,994 8 5/8 Surf - 4600	., 2002	1.7	2216 6	Unat	220			•
15. Elevation (Show whether DF, RT, CR, etc.)  3882 DF  12. County  Lea  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) see RULE 1708.  8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot  36 Sx plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 Sx plug in and out of 5½ casing. Stub @ 5952. Spotted 25 Sx plug in and out of base of  8 5/8" casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600	UNIT LETTER	<u> </u>	2310.0 FEET	FROM THE WEST	LINE AND	FEET FROM	GINGIOIN	Desouran
15. Elevation (Show whether DF, RT, CR, etc.)  3882 DF  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  TEMPORARILY ABANDON  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propositions/) SEE RULE 1708.  8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot 36 Sx plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 Sx plug in and out of 5½ casing stub @ 5952. Spotted 25 Sx plug in and out of 5½ casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600	Q au & L		7	105	20 1	•		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1708.  8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot 36 Sx plug @ 10,943 to 11,233. Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 Sx plug in and out of 5½ casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600	THE BOULD	LINE, SEC	TION	TOWNSHIP	HANGE	NMPM.	IIIIIII	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propositions/) SEE RULE 1708.  8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot 36 Sx plug @ 10,943 to 11,233. Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 Sx plug in and out of 5½ casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface. Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600	mmm	mm	15. F	levation (Show whether	DF. RT. GR. etc.)	· · · · · · · · · · · · · · · · · · ·	12. County	<i>·////////////////////////////////////</i>
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CABING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propositions)  8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mid. Spot  36 Sx plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 Sx plug in and out of 5½ casing stub @ 5952. Spotted 25 Sx plug in and out of base of 8 5/8" casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600					21, 11, 01, 010,		1 '	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1703.  8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot 36 \$x plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 \$x plug in and out of 5½ casing stub @ 5952. Spotted 25 \$x plug in and out of base of 8 5/8" casing. Spotted 15 \$x plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600	<del>'mm</del>	7777777	<u> </u>		<del></del>		L	
77. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE'1703.  8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot 36 \$x plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 \$x plug in and out of 5½ casing stub @ 5952. Spotted 25 \$x plug in and out of base of 8 5/8" casing. Spotted 15 \$x plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600		<del>-</del>		CHANGE BLANC	<b> </b>	<del></del>	PLUG	AND ABANDONMENT
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1703.  8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot 36 \$x plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 \$x plug in and out of 5½ casing stub @ 5952. Spotted 25 \$x plug in and out of base of 8 5/8" casing. Spotted 15 \$x plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600	PULL OR ALTER CASING	,		CHANGE PLANS	CASING TEST AND CE	MENT JQB		_
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propositions)  8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot 36 Sx plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 Sx plug in and out of 5½ casing stub @ 5952. Spotted 25 Sx plug in and out of base of 8 5/8" casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600				_	OTHER			
8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot 36 \$x plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 \$x plug in and out of 5½ casing stub @ 5952. Spotted 25 \$x plug in and out of base of 8 5/8" casing. Spotted 15 \$x plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600	OTHER							
8-17-67 Rigged up casing pullers. Ran Tubing and loaded hole with 10# mud. Spot 36 Sx plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 Sx plug in and out of 5½ casing stub @ 5952. Spotted 25 Sx plug in and out of base of 8 5/8" casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600	17. Describe Propose	d or Completed	Operations (Clearl	y state all pertinent de	tails, and give pertiner	nt dates, including	estimated date of	of starting any proposi
36 Sx plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 Sx plug in and out of 5½ casing stub @ 5952. Spotted 25 Sx plug in and out of base of 8 5/8" casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600			, ,					
36 Sx plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 Sx plug in and out of 5½ casing stub @ 5952. Spotted 25 Sx plug in and out of base of 8 5/8" casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600								
36 Sx plug @ 10,943 to 11,233.  Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 Sx plug in and out of 5½ casing stub @ 5952. Spotted 25 Sx plug in and out of base of 8 5/8" casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600	8-17-67	Rigged u	o casing ou	llers. Ran Tu	bing and load	ed hole wit	h 10# mud.	Spot
Rigged up to work 5½" casing. Casing parted @ 5952. Spotted 25 8x plug in and out of 5½ casing stub @ 5952. Spotted 25 8x plug in and out of base of 8 5/8" casing. Spotted 15 8x plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600	0 2, 0,							Opec
and out of 5½ casing stub @ 5952. Spotted 25 Sx plug in and out of base of 8 5/8" casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface.  Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600					sing parted @	5952. Spo	tted 25 Sx	nluo in
8 5/8" casing. Spotted 15 Sx plug in top of 8 5/8" casing @ surface. Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole 5½" 5952 - 11,994 8 5/8 Surf - 4600								
Installed marker. P & A 8-28-67  11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole $5\frac{1}{2}$ " 5952 - 11,994 8 5/8 Surf - 4600								
11-14-67 Lease cleaned up and ready for inspection.  Casing left in hole $5\frac{1}{2}$ " 5952 - 11,994 8 5/8 Surf - 4600							6	
Casing left in hole $5\frac{1}{2}$ " 5952 - 11,994 8 5/8 Surf - 4600								
	11-14-67	Lease cl	eaned up an	d ready for in	spection.			
13 3/8" Surf - 374		Casing 1	eft in hole	5½" 595	52 - 11,994	8 5/8	Surf - 4	600
		_						

John W. Reingen HILE (200)

DATE \_\_\_\_

J. M. Denson TITLE Asst. Dist. Manager of Prod. DATE November 14, 1967