

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator BILL FENN, INC.	8. Farm or Lease Name TAYLOR
3. Address of Operator P. O. DRAWER 569, GIDDINGS, TEXAS 78942	9. Well No. 4
4. Location of Well UNIT LETTER H 1980 FEET FROM THE NORTH LINE AND 660 FEET FROM THE EAST LINE, SECTION 7 TOWNSHIP 12SOUTH RANGE 38 EAST N.M.P.M.	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3868.2 GR	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

P & A REPORT

NOVEMBER 6, 1986  
NO CASING WAS RUN  
SET PLUGS AS FOLLOWS:

1. SET 100 FT. PLUG - 35 SX. FROM 5150 to 5050 FT.
2. SET 100 FT. PLUG - 35 SX. FROM 4550 TO 4450 FT.
3. SET 100 FT. PLUG - 35 SX. FROM 2450 TO 2350 FT.
4. SET 100 FT PLUG 425 FT. TO 325 FT. - 35 SX.
5. FILL INTERVAL WITH 96 MUD.
6. SET 10 SX. PLUG 25 FEET & ERECT DRY HOLE MARKER.

WELL WAS PLUGGED AS BEFORE RE-ENTRY.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Penny Brown</u>	TITLE <u>OPERATIONS MANAGER</u>	DATE <u>7/27/89</u>
APPROVED BY <u>Jack Griffin</u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>AUG 2 1989</u>