

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Orig&2cc: OOC, Hobbs
cc: Regional Office
cc: file

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Sinclair Oil Corporation Merged</u>	7. Unit Agreement Name
2. Name of Operator <u>SINCLAIR OIL & GAS COMPANY</u> <u>into Atlantic Richfield Company</u> <u>effective March 4, 1969</u>	8. Farm or Lease Name <u>Henry A. Harris</u>
3. Address of Operator <u>P. O. Box 1920, Hobbs, New Mexico 88240</u>	9. Well No. <u>2</u>
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>18</u> TOWNSHIP <u>12S</u> RANGE <u>38E</u> NMPM.	10. Field and Pool, or Wildcat <u>Gladiola Devonian</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3870' GR</u>	12. County <u>Lea</u>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PBTD 11,988' - 13-3/8"OD 48# casing set @ 307' and 350 sacks cement circulated to surface. 9-5/8"OD 36# and 40# casing set @ 4500' and cemented w/2100 sacks. Top cement behind 9-5/8"OD casing @ 1290' from surface. 5-1/2"OD 17# and 20# casing set @ 11,988' and cemented w/150 sacks. Cement top @ 11,340' from surface.

5-1/2"OD casing perforated 11,964-11,988'.

PROPOSE TO PLUG AND ABANDON AS FOLLOWS:

Place heavy mud between all plugs.

Set C. I. plug @ 11,900' w/2 sacks cement on top.

Cut off and pull approx. 5,000' of 5-1/2"OD casing, spot 25 sacks cement plug in top of 5-1/2"OD casing stub.

Spot 25 sacks cement plug, bottom of 9-5/8"OD intermediate casing @ approx. 4500'.

Cut off and pull approx. 500' of 9-5/8"OD casing.

Spot 25 sacks cement plug @ top of the 9-5/8"OD casing stub.

Spot 25 sacks cement plug @ bottom of 13-3/8"OD surface casing.

Cut off surface casing 5' below ground level, load hole from a depth of 20' to the surface w/cement. Set regulation dry hole marker, clean and level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Superintendent</u>	DATE <u>4-5-68</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR IN CHARGE</u>	DATE <u>APR 8 1968</u>
CONDITIONS OF APPROVAL, IF ANY:		