	4			Form C-103
OF COPIES RECEIVED	<i>4</i>			Supersedes Old
ISTRIBUTION	NEW HEYICO OII	_ CONSERVATION CO	DUMISSION	C-102 and C-103 Effective 1-1-65
AFE			7MM(199101V	2
<u> </u>	Orig&3cc: OCC, H		, г	5a. Indicate Type of Lease
G.S.	cc: Southe	rn Region (West	Texas)	State Fee X
ID OFFICE	cc: Partne	rs	}	5. State Oil & Gas Lease No.
ERATOR	cc: file			J. Blate Ch & das Lease No.
				mmmmmm
SUNDR (DO NOT USE THIS FORM FOR PRE USE "APPLICAT	NOTICES AND REPOR	TS ON WELLS R PLUG BACK TO A DIFFERI FOR SUCH PROPOSALS.)	ENT RESERVOIR.	7, Unit Agreement Name
OIL GAS				7. Unit Agreement Hume
WELL X WELL	OTHER-			8. Farm or Lease Name
Jame of Operator				Rosa Shults
SINCLAIR OIL COPPORAT	IOII			9. Well No.
Address of Operator				9. Well No.
P. O. Eox 1920, Hobbs	, New Mexico 88240	i		2
Location of Well				10. Field and Pool, or Wildcat
UNIT LETTER	310 FEET FROM THE W	est Line and	330 FEET FROM	Gladiola Devonian
South	ON18TOWNSHIP_	128	38E NMPM.	
THE LINE, SECTI	ON TOWNSHIP	HANGE	NW.	
mmm	15. Elevation (Show	whether DF, RT, GR, et	(c.)	12. County
		3873 GR		Lea
			D 0.1	D
	Appropriate Box To Indi	icate Nature of No	tice, Report or Oth	er Data
NOTICE OF 1	NTENTION TO:		SUBSEQUENT	REPORT OF:
			<u> </u>	<u></u>
PERFORM REMEDIAL WORK	PLUG AND ABAN	DON X REMEDIAL WOR	₹К	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DR	ILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST A	AND CEMENT JOB	
Pace on Aziran and in		OTHER		
OTHER				
<u> </u>				
17. Describe Proposed or Completed C	perations (Clearly state all pert	inent details, and give p	ertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.				
Presently completed	n Devonian peris.	LL,930'. I.D.	11,900. PDID 1	1,940.
13-3/8"OD casing set	303' and cemented	1 W/350 sks. to	surface.	•
9-5/8"OD csg. set @ 3	303' and cemented wa	7350 sks. to su	rlace.	0.33 0.01 0
7"OD csg. set @ 11,93	35' w/150 sks. cemer	it. Top of cem	ent behind 7"0D	csg @ 11,250' from
surface.				
PROFOSE TO PLUG AND A	ABANDON AS FOLLOWS:			
Fill hole w/heavy muc	d laden material.			
Set C.I. bridge plug	@ approx. 11,921' t	N/2 sks. cement	on top.	
Cut 7"OD csg @ 11,000	O' and pull.	•		
Spot 25 sks. cement	olug top of 7"OD cs	g. Stub @ 11,00	001.	
Spot 35 sks. cement	olug top of Penn @	95171.		
Spot 35 sks. cement	olug top of Wolfcam	n @ 90871.		,
Spot 35 sks. cement	olug top of Abo 7	8241		
Spot 35 sks. cement	olug top of Gloriets	59201		
Spot 25 sks. cement	olug bottom of 9-5/	RUOD csc O 1.52	D1.1	
Spot 2) sks. cement	plug bottom of 7-5/	81100 csg and ce	allar.install re	egulation dry hole marker
		5 - D C D C C C C C C C C C C C C C C C C	/1.2d1 , 1110 0 0 1 1 0	
clean and level loca	0.1011.			
\sim			<u> </u>	
18. I hereby certify that the information	on above is true and complete to	the best of my knowledg	e and belief.	
V NH				
L. oll bar		Superint	terd ent	DATE 3-4-69
SIGNED TO				
Va Don't	177.00			DATE
APPROVED BY	THE THE PARTY THE	/TLE		
CONDITIONS OF APPROVAL, IF AN				
CONDITIONS OF APPROVAL, IF AN	ıv:			