

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER-  
1. Name of Operator  
SKELTON OIL CO.  
2. Address of Operator  
P. O. Box 176, Hobbs, New Mexico 88240  
3. Location of Well  
UNIT LETTER K 1650 FEET FROM THE South LINE AND 2310 FEET FROM  
THE West LINE, SECTION 18 TOWNSHIP 12 S RANGE 38E NMPM.

7. Unit Agreement Name  
8. Farm or Lease Name  
BOBBIE  
9. Well No.  
3  
10. Field and Pool, or WHdcat  
GLADIOLA WOLF CAMP  
11. Elevation (Show whether DF, RT, GR, etc.)  
12. County  
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLUG AND ABANDON PROCEDURE:  
Dump 35' cement on CIBP SET at 9805.  
Set CIBP at 9400' (+ OR -) and dump 35' cement.  
Cement Plug w/20<sup>25</sup> sacks at 7134'.  
Mud to next plug.  
Cement plug w/20<sup>25</sup> sacks at 4432'.  
Mud to next plug.  
Cement plug w/20<sup>25</sup> sacks at 3000'.  
Mud to next plug.  
Cement plug w/35 sacks at 2000'.  
Mud to 10' from surface.  
Cement to Surface w/Dry hole Marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

19. Signed by Bobbie Skelton TITLE Owner-Operator DATE 7-24-87  
20. Approved by Paul Kautz TITLE Geologist DATE JUL 24 1987  
21. CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
JUL 24 1987  
OCU  
HOBBS OFFICE