

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL & GAS COMMISSION
 orig&cc: OGC, Hobbs
 cc: Southern Region (West Texas)
 cc: Partners
 cc: file

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> P&A GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator ATLANTIC RICHFIELD COMPANY 3. Address of Operator P. O. Box 1920, Hobbs, New Mexico 88240 4. Location of Well UNIT LETTER <u>K</u> <u>2310</u> FEET FROM THE <u>West</u> LINE AND <u>1650</u> FEET FROM THE <u>South</u> LINE, SECTION <u>18</u> TOWNSHIP <u>12S</u> RANGE <u>38E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3873' GR	7. Unit Agreement Name 8. Farm or Lease Name Rosa Shults 9. Well No. 3 10. Field and Pool, or Wildcat Gladiola Devonian 12. County Lea
--	--

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-5-69 Set C.I. Plug in 5-1/2"OD casing @ 11,890' w/2 sks. cement to 11,875'.
 to Jet perf. 5-1/2"OD casing 9400-9401' w/4-3/8" holes. Set C.I. Retainer @ 9330'
 4-19-69 and squeeze cement perms. 9400-01' thru 5-1/2"OD csg w/100 sks. Incor plus 3/4
 of 1% CFR2 Max. Press. 2800#. Filled hole w/heavy mud. Shot 5-1/2"OD casing off
 @ 4990' and pulled. Spotted 35 sacks cement plug in 5-1/2"OD csg stub @ 4990'.
 Spotted 50 sacks cement in bottom of 8-5/8"OD casing @ 4625'. Spotted 10 sks.
 cement plug in top of 8-5/8"OD csg and 13-3/8"OD casing and cellar @ surface.
 Installed regulation dry hole marker, cleaned and levelled location. P&A eff
 4-19-69.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Superintendent</u>	DATE <u>5-28-69</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>[Signature]</u>	DATE <u>SEP 30 1969</u>
CONDITIONS OF APPROVAL, IF ANY:		