

STATE OF NEW MEXICO
AND MINERALS DEPARTMENT

| | | |
|-----------------------|--|--|
| 8. OF COPIES RECEIVED | | |
| DISTRIBUTION | | |
| ANTA FE | | |
| ILZ | | |
| S.G.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

| | |
|--------------------------------|---|
| 5a. Indicate Type of Lease | |
| State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No. | |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- ☒

Salt water disposal well

Name of Operator

Rice Engineering & Operating, Inc.

Address of Operator

122 W. Taylor, Hobbs, New Mexico 88240

Location of Well

UNIT LETTER J 1980 FEET FROM THE south LINE AND 1980 FEET FROM

THE east LINE, SECTION 19 TOWNSHIP 12S RANGE 38E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

GL 3865'

7. Unit Agreement Name

8. Farm or Lease Name

Gladiola SWD "J"

9. Well No.

J-19

10. Field and Pool, or Wildcat

Gladiola

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-25-84: Pulled 4070' 7" OD buttress casing. Attempt to pull additional stuck to 5 1/2"/5" OD csg/tbg with top at 4102' was unsuccessful. Ran 2" tbg and tagged solid scale plug @ 11,920'. Ran in wire line to probable scale fill @ 11,816', pulled up and perforated 4 holes @ 11,800' in 5" stuck csg. Set 100 sack cement plug from 9140' (tagged) to 10,180' (calculated). Set 25 sack cement plug calculated to be from 4015' to 4165' in top of 7" OD csg and 8-5/8" OD csg. Set 35 sack cement plug calculated to be from 1920' to 2130' in 8-5/8" csg.

1-17-85: Set 6 sack cement plug from surface to 21' and installed P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

L. B. Goodheart

TITLE

Division Manager

DATE

2-4-85

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

FEB - 6 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB - 5 1985

O.C.D.
HOBBS OFFICE