## STATE OF NEW MEXICO ENERGY AND MINIERALS DEPARTMENT

46, 6F COPICS SECEIVES	1	•
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

## OIL CONSERVATION DIVISION

Same Classes   Source   Sour	DISTRIBUTION SANTA FE	<b>_</b>	P. O. 80		•		Form C-103 Revised 10-1-2
State   Stat	<u> </u>	SANT	A FE, NEW	MEXICO 87501			
SUNDRY NOTICES AND REPORTS ON WELLS  GOVERNMENT OF THE PROPERTY OF THE PROPERT	<u> </u>	<del> </del>		•		Sa. Indicate Type	of Lease
SUNDRY NOTICES AND REPORTS ON WELLS  The state of the control of the contro						State	5 V
SUNDRY NOTICES AND REPORTS ON WELLS  1. Nome of Common Services Control of Services Co		-		•			
Thereby certify that the information above is the and complete to the base of an exactance of a pump. Pull to production.  Petrus Oil Company, L. P.  1. Address of Company, L. P.  1. Add	orenation .					J, 5,6,6 On & 542	. Fadea Wo.
Thereby certify that the information above is the and complete to the base of an exactance of a pump. Pull to production.  Petrus Oil Company, L. P.  1. Address of Company, L. P.  1. Add	SLINI	DRY NOTICES AND E	EDODIE ON	WELLE	<del> · · </del>	mmm	minim
There of Cornelles    Note of Cornelles   Note of Cornelles	OG NOT USE THIS FORM FOR	PROPOSALS TO DRILL OR TO D	EPURIS UN	WELLS ACK TO'A DIFFERENT RESERV	OIR.		
New of Operator   Petrus Oil Company, L. P.	1.	.2.104 FOR FERMIT 2 (FOR	- (-701) FOR SUL	N PROPOSALS.)	······································	7 Unit Agreement	77777777
A. Team of Lesses home Potrus Oil Company, L. P.  1. Address of Operator Potrus Oil Company, L. P.  1. Address of Operator Potrus Oil Company, L. P.  1. Address of Operator Potrus Oil Company, L. P.  1. Address of Operator Potrus Oil Company, L. P.  1. Address of Operator Potrus Oil Company, L. P.  1. Address of Operator Potrus Oil Company, L. P.  1. Address of Operator Potrus Oil Company, L. P.  1. Address of Operator Potrus Oil Company, L. P.  1. Address of Operator Potrus Oil Company, L. P.  1. Address of Operator Potrus Oil Company, L. P.  1. Address of Operator Potrus Oil Company, L. P.  1. Address of Operator Potrus Oil Company Potrus Oil Company, L. P.  1. Address of Operator Potrus Oil Company Potru	OIL X GAS	A7468-				71 Omi Agreement	· · · · · · · · · · · · · · · · · · ·
Petrus Oil Company, L. P.  1. Address of Operation 12201 Merit Drive, Suite 900  Dallas, Texas 75251  1. Location of Well  unit cetter  L2310		01164-	<del></del>	<del></del>	<del></del>	8 Form or Lease	Name -
1. Address a Operator   1201 Merit Drive, Suite 900   Dallas, Texas 75251   1   1   1   1   1   1   1   1   1		, † D					
12201 Merit Drive, Suite 900  Dallas, Texas 75251  10. Field and Fell, or Widden (Cladiclasses)  Nest		, L. F.					on ''A''
County   12   12   13   13   14   15   15   15   15   15   15   15		C	D 11	T		9. Well No.	
South circa		Suite 900	Dallas,	Texas 75251		1	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:    Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:    Subsequent Report of Subsequent Report o	4. Location of Well				İ		•
**************************************	UNIT LETTER	2310 PEET FROM TH	South	LINE AND330	PERT FROM	Gladiola-I	Devonian
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  **CLAPTION TO:  **CLAPTION TREPORT OF:  **CLAPTION TR							
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  **CLAPTION TO:  **CLAPTION TREPORT OF:  **CLAPTION TR	west	19	12	7.0			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PLUE AND ABANDOM  PLUE OF ALTERING CASING  PULL TOOLS  Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see while 1102.  Propose to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-9424';9431-9437';9452-9456';9466-9470';9472-9476';9485-9489';9501-9507  9526-9552';9536-9552';9536-9552'. Selectively acidize each interval will buil of 158 NEFE acid for total of 3000 gals. Displace w/2% KCI. Rerun tbg, rods & pump. Return well to production.  ALTERING CASING  ALTERING CASING  ALTERING CASING  PLUE AND ABANDOM COMMENT TO THE ALTERING CASING  PLUE ABANDOM COMMENT TO THE ALTERING CASING  ALTERING CASING CASING CASING		1 0W		NANGE	NMPM.		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PLUE AND ABANDOM  PLUE OF ALTERING CASING  PULL TOOLS  Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see while 1102.  Propose to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-9424';9431-9437';9452-9456';9466-9470';9472-9476';9485-9489';9501-9507  9526-9552';9536-9552';9536-9552'. Selectively acidize each interval will buil of 158 NEFE acid for total of 3000 gals. Displace w/2% KCI. Rerun tbg, rods & pump. Return well to production.  ALTERING CASING  ALTERING CASING  ALTERING CASING  PLUE AND ABANDOM COMMENT TO THE ALTERING CASING  PLUE ABANDOM COMMENT TO THE ALTERING CASING  ALTERING CASING CASING CASING		15. Elevation	(Show whether	OF, RT, GR, etc.)		12. County	<del>/////////////////////////////////////</del>
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:    Check Appropriate Box To Indicate Nature of Notice, Report or Other Data   Subsequent Report of:   Check Appropriate Subsequent Report of Propriate Subsequent Report							
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMINIAL WORL  TREMPORABLY ARABOON  PILLO RALER CASING  CHAMBE PLAND  CH	16.						ann
Propose to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'. Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-9424';9431-9437';9452-9456';9466-9470';9472-9476';9485-9489';9492-9496';9501-9507' 9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KCl. Rerun tbg, rods & pump. Return well to production.  1.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.  2.2 hereby certify that the information above is true and complete to the best of my knowledge and belief.  2.3 hereby certify that the information above is true and complete to the best of my knowledge and belief.  2.4 hereby certify that the information above is true and complete to the best of my knowledge and belief.  2.5 hereby certify that the information above is true and complete to the best of my knowledge and belief.  2.6 hereby certify that the information above is true and complete to the best of my knowledge and belief.  2.7 hereby certify that the information above is true and complete to the best of my knowledge and belief.  2.8 hereby certify that the information above is true and complete to the best of my knowledge and belief.  2.9 hereby certify that the information above is true and complete to the best of my knowledge and belief.  2.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.  2.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.  2.2 hereby certify that the information above is true and complete to the best of my knowledge and belief.  2.3 hereby certify that the information above is true and complete to the best of my knowledge and belief.  2.4 hereby certify that the information above is true and complete to the best of my knowledge and belief.			o Indicate N	ature of Notice, Rep	ort or Othe	er Data	
Propose to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'. Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-9424';9431-9437';9452-9456';9466-9470';9472-9476';9485-9489';9501-9507' 9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KCl. Rerun tbg, rods & pump. Return well to production.  Displace belief.  Regulatory Coordinator  Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed with the later of the proposed of the pertinent dates, including estimated date of starting any proposed with the later of total control of total control of the pertinent details, and give pertinent dates, including estimated date of starting any proposed with the later of total control of the pertinent details, and give pertinent dates, including estimated date of starting any proposed with the later of the pertinent dates, including estimated date of starting any proposed with the later of the pertinent dates, including estimated date of starting any proposed with the later of the pertinent dates, including estimated dates of starting any proposed with the later of the pertinent dates.  Proposed to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Proposed to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Proposed to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Proposed to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Proposed to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Proposed to do the following work.  Pull rods & pump. Pull tubing anchor. Set Baker Model "S	NOTICE OF	INTENTION TO:		SUE	SEQUENT	REPORT OF:	
Propose to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'. Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-9424';9431-9437';9452-9456';9466-9470';9472-9476';9485-9489';9501-9507' 9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KCl. Rerun tbg, rods & pump. Return well to production.  Displace belief.  Regulatory Coordinator  Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed with the later of the proposed of the pertinent dates, including estimated date of starting any proposed with the later of total control of total control of the pertinent details, and give pertinent dates, including estimated date of starting any proposed with the later of total control of the pertinent details, and give pertinent dates, including estimated date of starting any proposed with the later of the pertinent dates, including estimated date of starting any proposed with the later of the pertinent dates, including estimated date of starting any proposed with the later of the pertinent dates, including estimated dates of starting any proposed with the later of the pertinent dates.  Proposed to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Proposed to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Proposed to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Proposed to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Proposed to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Proposed to do the following work.  Pull rods & pump. Pull tubing anchor. Set Baker Model "S							
CASING TEST AND CENSENT JOB  OTHER  7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.  Propose to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'. Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-942';9431-945';9452-9456';9466-9470';9472-9476';9485-9489';9492-9496';9501-9507' 9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KCl. Rerun tbg, rods & pump. Return well to production.  Displace W/2% KCl. Regulatory Coordinator production.  MAY 2 7 1987  MAY 2 7 1987	PERFORM REMEDIAL WORK	PLUS AN	D ASANDON	REMEDIAL WORL		ALTERIN	G CASING
CASING TEST AND CENSENT JOB  OTHER  7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.  Propose to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'. Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-942';9431-945';9452-9456';9466-9470';9472-9476';9485-9489';9492-9496';9501-9507' 9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KCl. Rerun tbg, rods & pump. Return well to production.  Displace W/2% KCl. Regulatory Coordinator production.  MAY 2 7 1987  MAY 2 7 1987	TEMPORARILY ASANOON		_	COMMENCE DRILLING OPHS.	i i i		<u> </u>
7. Desectible Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE MULE 1703.  Propose to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'. Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-9424';9431-9437';9452-9456';9466-9470';9472-9476';9485-9489';9492-9496';9501-9507-9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KC1. Rerun tbg, rods & pump. Return well to production.  All hereby certify that the information above is true and complete to the best of my vnowledge and belief.  Proposed or Completed date of starting any proposed and selection of the perton of t	PULL OR ALTER CASING	CHANGE	PLANS		<del></del>		
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE NULE 1703.  Propose to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'. Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-9424';9431-9437';9452-9456';9466-9470';9472-9476';9483-9489';9492-9496';9501-9507 9526-9552';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KC1. Rerun tbg, rods & pump. Return well to production.  1. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my knowledge.  3. I hereby certify that the information above is true and complete to the best of my knowledge.  3. I hereby certify that the information above is true and complete to the best of my knowledge.		-	-1		~ <u>_</u>		
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE Note: 103.  Propose to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'. Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-9424';9431-9437';9452-9456';9466-9470';9472-9476';9485-9489';9492-9496';9501-9507-9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KCl. Rerun tbg, rods & pump. Return well to production.  Propose to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Pull rods & pump and pump and pump and part of the perton with the logical part of the perton with the part of the perton with the part of the perton with th	OTHER						
Propose to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-9424';9431-9437';9452-9456';9466-9470';9472-9476';9485-9489';9492-9496';9501-9507 9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KC1. Rerun tbg, rods & pump. Return well to production.  Displace w/2% KC1. Rerun tbg, rods & pump. Return well to production.  All hereby certify that the information above is true and complete to the best of my vnowledge and belief.  ORIGINAL SIGNED BY JERRY SEXTON  DISTRICT I SUPERVISOR  MAY 2 7 1987							
Propose to do the following work.  Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'.  Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-9424';9431-9437';9452-9456';9466-9470';9472-9476';9485-9489';9492-9496';9501-9507 9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KC1. Rerun tbg, rods & pump. Return well to production.  Displace w/2% KC1. Rerun tbg, rods & pump. Return well to production.  All hereby certify that the information above is true and complete to the best of my vnowledge and belief.  ORIGINAL SIGNED BY JERRY SEXTON  DISTRICT I SUPERVISOR  MAY 2 7 1987	17. Describe Proposed or Completed	Operations (Clearly state a	ll pertinent desa	ils, and give pertinent date	s, including e	stimated date of sta	urting any proposed
Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'. Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-9424';9431-9437';9452-9456';9466-9470';9472-9476';9485-9489';9492-9496';9501-9507 9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KCl. Rerun tbg, rods & pump. Return well to production.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.	WORK) SEE NULE 1103.						
Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'. Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-9424';9431-9437';9452-9456';9466-9470';9472-9476';9485-9489';9492-9496';9501-9507 9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KCl. Rerun tbg, rods & pump. Return well to production.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.							
Pull rods & pump. Pull tubing and tubing anchor. Set Baker Model "S" CIBP @ 11,700'. Dump bail 20' cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404';9410-9416'; 9420-9424';9431-9437';9452-9456';9466-9470';9472-9476';9485-9489';9492-9496';9501-9507 9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KCl. Rerun tbg, rods & pump. Return well to production.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  1. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  2. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.	Propose to do the	following work.					
Dump Ball 20° cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404";9410-9416"; 9420-9424";9431-9437";9452-9456";9466-9470";9472-9476";9485-9489";9492-9496";9501-9507 9526-9532";9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KC1. Rerun tbg, rods & pump. Return well to production.  Displace w/2% KC1. Rerun tbg, rods & pump. Return well to production.  Return well to production.  ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  MAY 2 7 1987	1						
Dump Ball 20° cmt on top. Perforate w/1 spf w/4-1/8" csg gun 9398-9404";9410-9416"; 9420-9424";9431-9437";9452-9456";9466-9470";9472-9476";9485-9489";9492-9496";9501-9507 9526-9532";9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KC1. Rerun tbg, rods & pump. Return well to production.  Displace w/2% KC1. Rerun tbg, rods & pump. Return well to production.  Return well to production.  ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  MAY 2 7 1987	Pull rode & n	umn Dull tuhin	a and tubi		D 1 14		
9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KC1. Rerun tbg, rods & pump. Return well to production.  9. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  9. ORIGINAL SIGNED BY JERRY SEXTON  DISTRICT I SUPERVISOR  MAY 2 7 1987	Dump bail 201	omp. ruii tubin	g and tubi	ng anchor. Set	Baker Mo	dei "S" CIBP	9 @ 11,700'.
9526-9532';9536-9542. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KC1. Rerun tbg, rods & pump. Return well to production.  9. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  9. ORIGINAL SIGNED BY JERRY SEXTON  DISTRICT I SUPERVISOR  MAY 2 7 1987	0420 04241-04	71 04771 0452 04	riorate w/	1 spf $w/4-1/8''$ c	sg gun 9:	398-9404';94	10-9416';
9320-9332';9330-9342. Selectively acidize each interval w/1 bbl of 15% NEFE acid for total of 3000 gals. Displace w/2% KCl. Rerun tbg, rods & pump. Return well to production.  3. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.  4. I hereby certify that the information above is true and complete to the best of my vnowledge and belief.	3440-3424 ,34	31-943/ : 9432-94:	50':9466-9	4/0':94/2-9476'・	9485_9489	91.9492_9496	1.0501 0507
B. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  Suzann Jourdan virte Regulatory Coordinator DATE 05-18-87  ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	9520-95521;95	30-9542. Select:	ivelv acid	ize each interva	$1 \text{ w}/1 \text{ hh}^{2}$	1 of 15% NED	E acid for
S. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  Suzann Jourdan VITLE Regulatory Coordinator DATE 05-18-87  ORIGINAL SIGNED BY JERRY SEXTON  DISTRICT I SUPERVISOR  MAY 2 7 1987	total of 3000	gals. Displace	W/2% KC1.	Rerun tbg, rod	s & pump	. Return we	11 to
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  Regulatory Coordinator  Regulatory Coordinator  MAY 2 7 1987	production.						
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  Regulatory Coordinator  Regulatory Coordinator  MAY 2 7 1987							
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  Regulatory Coordinator  Regulatory Coordinator  MAY 2 7 1987							
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  Regulatory Coordinator  Regulatory Coordinator  MAY 2 7 1987							
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  Regulatory Coordinator  Regulatory Coordinator  MAY 2 7 1987							
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  Regulatory Coordinator  Regulatory Coordinator  MAY 2 7 1987							
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  Regulatory Coordinator  Regulatory Coordinator  MAY 2 7 1987				•			
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  Regulatory Coordinator  Regulatory Coordinator  MAY 2 7 1987							
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  Regulatory Coordinator  Regulatory Coordinator  MAY 2 7 1987							
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  Regulatory Coordinator  Regulatory Coordinator  MAY 2 7 1987		·					
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  Regulatory Coordinator  Regulatory Coordinator  MAY 2 7 1987							
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  Regulatory Coordinator  Regulatory Coordinator  MAY 2 7 1987	O I books and the books to be before			<del></del>			
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  MAY 2 7 1987	5. I nereby certify that the information $\sim$	m above is true and comple	te to the best of	my knowledge and belief.			
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  MAY 2 7 1987	1						
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  MAY 2 7 1987	IENED Suran Jourda	-Suzann Jourdan	TITLER	egulatory Coordi	nator	DATE 05-1	8-87
DISTRICT I SUPERVISOR WAY 2 / 198/							
DISTRICT I SUPERVISOR ITIM I & ( IDO)				•		MAV	7 1007
TITLE NAME	DISTRICT I SU	PERVISOR	TITLE			MIMI A	, ( 130/

HORAS OCH BOY

en de la companya de