

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>30-025-07218</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION	7. Lease Name or Unit Agreement Name BRONCO WOLFCAMP UNIT
2. Name of Operator GP II ENERGY CORPORATION	8. Well No. 7
3. Address of Operator P.O. BOX 50682 MIDLAND, TEXAS 79702	9. Pool name or Wildcat BRONCO WOLFCAMP
4. Well Location Unit Letter <u>J</u> : <u>2110</u> Feet From The <u>SOUTH</u> Line and <u>1813</u> Feet From The <u>EAST</u> Line Section <u>2</u> Township <u>13-S</u> Range <u>38-E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3810' RKB</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SET 5-1/2" CIBP @ 9000'; CAP W/ 35' CMT.  
CIRC HOLE W/ 10# BRINE W/ 25# SALT GEL PER BBL.  
SPOT 50 SXS; 50' IN & 50' OUT 5-1/2" CSG STUB; WOC & TAG.  
SPOT 50 SXS 4622'-4522' (8-5/8" CSG SHOE); WOC & TAG.  
SPOT 45 SXS 375'-275' (13-3/8" CSG SHOE). *will need to perf @ 5/8" @ 375'*  
SPOT 15 SXS 30'-SURFACE.  
INSTALL DRY HOLE MARKER

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joey Fields TITLE AGENT DATE 7-15-96  
TYPE OR PRINT NAME JOEY FIELDS TELEPHONE NO. (915)563-0430

(This space for State Use)

JUL 19 1996

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: