

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name Barnes & Golden
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>11</u> TOWNSHIP <u>13S</u> RANGE <u>38E</u> NMPM.		10. Field and Pool, or Wildcat Mississippian
15. Elevation (Show whether DF, RT, GR, etc.) 3800' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Perforate, acidize & test</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

On 10/29/75 tested tbg hd & 5 1/2" csg to 1500# for 30 mins OK. Perforated 2 JSPF ea @ 10,983, 90, 93, 96, 99, 11,002, 05, 08, 11 & 11,014' = 20 holes. New PBD @ 11,408'. RIH w/tbg & pkr, set pkr @ 10,914'. Press up on csg to 1000# OK. Treated perms 10,983-11,014' w/8000 gal retarded 20% HCLNE acid followed by 8000 gal 15% HCLNE acid, flushed w/54 BBW. MP 3800#, Min 2100#, ISIP 0#. On 11/1/75, 14 hr SITP 25#, CP 0#. Swbd 8 hrs, rec 188 BLW & 67 BFW, no oil or gas. On 11/3/75, 40 hr SITP 25#, CP 0#. Swbd 9 1/2 hrs, rec 281 BFW, no oil or gas. POH w/tbg & pkr. RIH w/191 jts 5966' of 2-3/8" OD EUE tbg open ended. Installed wellhead & 2000# WOG valve on tbg. Shut well in. Temporarily abandoned effective 11/4/75. Recompletion unsuccessful. Well to be recommended for plugging & abandonment.

Expires 12/1/76

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Dist. Drlg. Supv. DATE 11/11/75

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: