






SPONTANEOUS-POTENTIAL millivolts	RESISTIVITY ohms. m/m	CONDUCTIVITY millimhos/m = $\frac{1000}{\text{ohm m}}$
COMPANY <u>RALPH LOWE</u>		SWC PR <u>15553</u>
WELL <u>SCHENCK #1</u>		SWC TO <u>15557</u>
FIELD <u>VILLAGAT</u>		DATE TO <u>1957</u>
COUNTY <u>LEA</u> STATE <u>NEW MEXICO</u>		Elev. <u>8887</u>
		DP <u>15557</u>
		OL <u>15557</u>

DETAIL LOG

SPONTANEOUS-POTENTIAL millivolts	RESISTIVITY ohms. m/m	CONDUCTIVITY millimhos/m = $\frac{1000}{\text{ohm m}}$	
- 20 - 10 +	16" NORMAL	INDUCTION	
	100	200	0
	1000		
	INDUCTION		
	100		
	1000		



- 20 - 10 +	16" NORMAL	INDUCTION
	100	200
	1000	
	INDUCTION	
	100	
	1000	
SPONTANEOUS-POTENTIAL millivolts	RESISTIVITY ohms. m/m	CONDUCTIVITY millimhos.
COMPANY <u>RALPH LOWE</u>	SWC PR <u>15553</u>	SWC TO <u>15557</u>
WELL <u>SCHENCK #1</u>	DATE TO <u>1957</u>	Elev. <u>8887</u>
FIELD <u>VILLAGAT</u>		DP <u>15557</u>
		OL <u>15557</u>