

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

3-NMCCC

1-FILE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-2576	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator GETTY OIL COMPANY	8. Farm or Lease Name STATE "BF"
3. Address of Operator P.O. BOX 840, ALBUQUERQUE, NEW MEXICO 87106	9. Well No. #1
4. Location of Well UNIT LETTER <u> </u> , <u>330</u> FEET FROM THE <u>NORTH</u> LINE AND <u>330</u> FEET FROM THE <u> </u> LINE, SECTION <u>47</u> TOWNSHIP <u>12-S</u> RANGE <u>34-N</u> N.M.P.M.	10. Field and Pool, or Wildcat RANGER LAKE-BOUGH C
15. Elevation (Show whether DF, RT, GR, etc.) 4153 GF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Attempted to run CIBP Plug. Stopped at 6436'. 11-10-73. Ran tubing to 8963'. Pumped 2 sx. of leather and 2 sx. of ropes. Shut in for 1-1/2 hr. Pumped 25 sx. of cement. Attempted to tag plug with Wire Line. Could not get down in tubing. Pressure tested well to 525 PSI. Shut in at 525 PSI for 5 min. Held pressure. Mixed mud and circulated hole.

Shot pipe at 4574'. Pulled and layed down pipe. 11-18-73.

Ran tubing to 4624' and pumped 30 sx. plug. Pulled tubing to 4330' and pumped a 45 sx. plug. 11-20-73.

Cut 8-5/8" casing at 1102'. Pulled and layed down 8-5/8" casing. 1-21-73.

Ran tubing to 1168' and pumped 45 sx. plug. Pulled tubing to 411 and spotted a 65 sx. plug. 11-24-73.

Placed 10 sx. surface plug and installed "DRY HOLE MARKER". 12-6-73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY:

SIGNED C. L. WADE: / C. L. Wade TITLE AREA SUPERINTENDENT DATE JANUARY 10, 1974

APPROVED BY John W. Phynan TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

WLG/bh