

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

API NO. 30-025-08448

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-906
7. Unit Agreement Name -----
8. Farm or Lease Name Ranger
9. Well No. 12
10. Field and Pool, or Wildcat Ranger Lake Bough
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Phillips Petroleum Company 3. Address of Operator Room 401, 4001 Penbrook St., Odessa, Texas 79762 4. Location of Well UNIT LETTER N, 660 FEET FROM THE South LINE AND 1830 FEET FROM THE West LINE, SECTION 26, TOWNSHIP 12-S, RANGE 34-E, NMPM.
---

15. Elevation (Show whether DF, RT, GR, etc.)

4157' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-20-80 MI Jamison and Caffey WS Unit. Displaced oil in hole w/wtr. Pulled tbg and pkr.

8-21/24-80 Dumped 3 sxs cmt on BP at 10,000'. Set BP at 9930'. Dumped 3 sxs cmt. Ran 2-3/8" tbg, circd hole w/mud. Spotted 50 sxs C1 "C" cmt at 6800'. Pulled tbg to 2800'. Spotted 100 sxs C1 "C" cmt. Pulled tbg.

8-25/26-80 Welded pull npl on 5-1/2" csg and 8-5/8" csg to remove slips; cut 5-1/2" csg at 1725'. Pulled and laid down 1725'.

8-27-80 Spotted 100 sxs C1 "C" cmt at 1775'. WOC 6 hrs, tagged plug at 1488'.

8-28-80 Spotted 35 sxs C1 "C" cmt from 100' to surface. MO Jamison and Caffey. Cut off well head and installed dry hole markers. Well P&A 8-28-80.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. J. Mueller

TITLE Sr. Engineering Specialist

DATE 9-3-80

OIL & GAS INSPECTOR

APPROVED BY W. J. Mueller  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE JAN 13 1981