

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

NO. OF COPIES RETURNED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State ☒	Fee ☐
3. State Oil & Gas Lease No.	
V-961	

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL UP TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT WITH FORM C-101 FOR SUCH PROPOSALS.)	
OIL WELL ☐ GAS WELL ☐ OTHER: Re-Entry	
Name of Operator Harvey E. Yates Company	
Address of Operator Box 1933, Roswell, NM 88201	
Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>5</u> TOWNSHIP <u>13-S</u> RANGE <u>33-E</u> NEPM.	
11. Elevation (Show whether DF, RT, GR, etc.) 4295' (GL)	
12. County Lea	

10. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☐ CHANGE PLANS ☐ REMEDIAL WORK ☐ COMMENCE DRILLING OPS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐
	ALTERING CASING ☐ PLUG AND ABANDONMENT ☒

17. Describe Proceed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

8-28-85: GIH & set CIBP @ 9450' w/35' cmt on top. Pump 100' plug from 8850-8750'.
 9-06-85: GIH & cut 5-1/2" csg @ 3750' POOH w/cutter & 89 jts csg.
 9-07-85: GIH & pump 400' plug @ 3780'. Tagged plug @ 3570'. Pump 100' plug @ 1640'. Pump 50' surface plug. Installed dry hole marker. P&A complete.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Stephen L. Lake TITLE Asst. Engineer DATE 9-12-85
 APPROVED BY Jack Bruffin TITLE OIL & GAS INSPECTOR DATE FEB 25 1987
 CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 16 1985

G.C.B.
HOBBS OFFICE