

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator IMPERIAL-AMERICAN MANAGEMENT COMPANY		8. Farm or Lease Name MAXWELL	
3. Address of Operator 215 Mid American Building, Midland, TX 79701		9. Well No. 1	
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM West 6 TOWNSHIP 13-S RANGE 38-E NMPM.		10. Field and Pool, or Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.) 3861 GR., 3873 KB.		12. County LEA	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP in 5-1/2" 20# csg @ 12,000'. Spot 6 sx cement on BP. (35')
2. Perforate 11,232-11,237 with 10 shots.
3. Acidize and swab test.
4. If productive, complete.
5. If non productive, set CIBP @ 10,000', spot 6 sx cement on BP. 35' cement.
6. Perforate Wolfcamp from 9,648-9,700'.
7. Acidize and test. If productive, complete.
8. If non productive, prepare to P&A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R. S. GUNTHER</u>	TITLE <u>Agent</u>	DATE <u>2-3-77</u>
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

FEB 1977

OIL CONSERVA. & COMM.
HOBBS, N. M.