

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO CONSERVATION COMMISSION

Nov 9 1 08 PM '65

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-3359
7. Unit Agreement Name --
8. Farm or Lease Name King
9. Well No. 1
10. Field and Pool, or Wildcat King Devonian
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator TRAINER CORPORATION
3. Address of Operator P. O. Box 1100, Hobbs, New Mexico
4. Location of Well UNIT LETTER P, 660 FEET FROM THE South LINE AND 330 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 14S RANGE 37E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3836 GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☒  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☒ *Farmer C. H. Trainer*

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

This well was plugged and abandoned as follows:

Plugging operations were commenced on October 16 and completed on October 24.

1. Spot 25 sx plug 12,300' - 12,688'.
2. Cut off 4 1/2" casing & pulled at 8248'.
3. Spot 25 sx. plug in and out of 4 1/2" casing stub.
4. 25 sx plug at 8248'.
5. 25 sx plug at 7300'.
6. 25 sx plug at 5600'.
7. Spot 25 sx. plug 4625'-4700'.
8. Cut off 9 5/8" casing at 1108'.
9. Spot 25 sx. plug in and out of 9 5/8" casing stub.
10. 25 sx. plug at 1108'.
11. Spot 25 sx. plug 275' - 325'.
12. Set regulation marker in 10 sx. at surface.
13. Level and clean location for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TRAINER CORPORATION

SIGNED BY: *C. H. Trainer* TITLE: President DATE: November 8, 1965

APPROVED BY: *John W. Rungas* TITLE: DATE:

CONDITIONS OF APPROVAL, IF ANY:

