

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

JUL 14 11 57 AM '65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. K-3359	
7. Unit Agreement Name --	
8. Farm or Lease Name King	
9. Well No. #1	
10. Field and Pool, or Wildcat King Devonian	
12. County Lea	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator C. W. TRAINER
3. Address of Operator P. O. Box 1100, Hobbs, New Mexico
4. Location of Well UNIT LETTER <u>P</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>14S</u> RANGE <u>37E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-9- Ran 396 jts. 4 1/2", J-55 & N-80 11.6# New Casing and set at 12,788'. Cemented w/400 sacks 50-50 Posmix, 2% gel and 18% salt. Spearheaded w/2,000 gallons H<sub>2</sub>O and Clay. Plug down at 5:40 AM.

7-12 5:40 AM - 6:00 PM. Run 4 1/2" casing, set head and bottom plug to 12,788' and cemented. 11:15 AM.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. W. Trainer TITLE Owner-Operator DATE 7-12-65  
APPROVED BY [Signature] TITLE  DATE   
CONDITIONS OF APPROVAL, IF ANY:

