	1	Form C -103
NO. OF COPIES RECEIVED		Supersedes Old
DISTRIBUTION		C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		5a. Indicate Type of Lease
J.S.G.S.		State X Fee
AND OFFICE		5. State Oil & Gas Lease No.
OPERATOR		E-1027
SUNDS (DO NOT USE THIS FORM FOR PR USE "APPLICA"	RY NOTICES AND REPORTS ON WELLS OF DOTICES AND REPORTS ON THE PROPOSALS.)	
OIL X GAS WELL	OTHER-	7. Unit Agreement Name
Name of Operator	· · · · · · · · · · · · · · · · · · ·	8. Farm or Lease Name
TEXACO Inc.		New Mexico 'CZ' State
. Address of Operator		9. Well No.
	S, NEW MEXICO 88240	1
. Location of Well		10. Field and Pool, or Wildcat
.1 1	1945 FEET FROM THE South LINE AND 1945 FEET FR	Ranger Lake (Penn)
	10 14 TOWNSHIP 12-S RANGE 34-E NMP	VIIIIIIIIIII
mmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4156' (DF)	Lea
16. Check	Appropriate Box To Indicate Nature of Notice, Report or C	Other Data
	NTENTION TO: SUBSEQUE	NT REPORT OF:
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMED!AL WORK	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	-
· · · · · · · · · · · · · · · · · · ·	OTHER	
OTHER		

The following work has been completed on subject well:

Pull production rods and pump.

mud up note.
 Spot 5 sx cement plug in 2-7/8" 0.D. casing from 9986' - 9820'. # Then 15 6x5 More
 Cut off 2-7/8" 0.D. casing @ 2600' (Calculated cement top) > 2595'
 Spot 25 sx. cement plug from 50' below to 50' above cut off.
 Spot 10 sx. cement plug @ surface.
 Set 4" dry hole marker extending 4' above ground level, clean location, plug and abandon, April 17, 1970.

18. I hereby certify that the information above is true and complete	ete to the best of my knowledge and belief.	
0111	Assistant District Superintendent	April 17, 1970
SIGNED ACCOUNTY	SUPERVISOR DISTRIC	v 2 j. 197 0
APPROVED BY	TITLE	DATE
ONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

APR 2 7, 1970

ON COMMENTATION CORM.