

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

OCT 15 1969

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>E-1027</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name -
2. Name of Operator <b>TEXACO Inc.</b>	8. Farm or Lease Name <b>New Mexico "CZ" State</b>
3. Address of Operator <b>P. O. Box 728 - Hobbs, New Mexico 88240</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>J</b> , <b>1945</b> FEET FROM THE <b>South</b> LINE AND <b>1945</b> FEET FROM THE <b>East</b> LINE, SECTION <b>14</b> TOWNSHIP <b>12-S</b> RANGE <b>34-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Ranger Lake (Penn)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4156' (DF)</b>	12. County <b>Lea</b>

16.

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOBS	<input type="checkbox"/>	OTHER	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TEXACO proposes to do the following work on subject well:

1. Pull production rods and pump.
2. Mud up hole.
3. Spot 5 sx. cement plug in 2-7/8" O.D. casing from 9986' - 9820'.
4. Cut off 2-7/8" O.D. casing @ 2600' (Calculated cement top)
5. Spot 25 sx. cement plug from 50' below to 50' above cut off.
6. Spot 10 sx. cement plug @ surface.
7. Set 4" dry hole marker extending 4' above ground level, clean location, and abandon.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

Assistant District  
Superintendent

DATE **October 15, 1969**

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE