

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>	
5. State Oil & Gas Lease No. -	
7. Unit Agreement Name -	
8. Farm or Lease Name G. A. Whitnire	
9. Well No. 1	
10. Field and Pool, or Wildcat Bronco-Devonian, West	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Ashmun & Hilliard 3. Address of Operator 303 N. Marienfeld St., Midland, Texas 79701 4. Location of Well UNIT LETTER "J" 2310 FEET FROM THE South LINE AND 2310 FEET FROM THE East LINE, SECTION 6 TOWNSHIP 13-S RANGE 38-E N.M.P.M. 15. Elevation (Show whether DF, RT, GR, etc.) 3857 - GL	7. Unit Agreement Name - 8. Farm or Lease Name G. A. Whitnire 9. Well No. 1 10. Field and Pool, or Wildcat Bronco-Devonian, West
--	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Commencing March 13, 1966, at 9:00 a.m., operator directed the plugging and abandonment as follows:

Shot off and pulled 1345' of 8 5/8" casing. Placed cement plugs as follows:

- 50' 25 sx plug set in top of stub of 8 5/8" casing**
- 50' 25 sx plug set in base of surface pipe at 1385'**
- 30' 10 sx plug set in top of surface pipe**
- 50' 25 sx plug set at TD 11,726'**
- 50' 25 sx plug set at top of Penn 9800'**
- 50' 25 sx plug set at top of Tubb 7285'**
- 50' 25 sx plug set at top of Glorieta 5995'**
- 50' 25 sx plug set at bottom of 8 5/8" casing 4565'**

Applied mud by pump between all cement plugs from TD back to surface. Surface marker set in top of cement. P & A operations completed at 6:00 p.m. on March 14, 1966. Left 3220' of 8 5/8" casing in hole and 383' of 11 3/4" surface casing in hole. Authorization to plug & abandon given by Joe Ramey verbally over phone at 8:00 March 13, 1966. Notification will be given when site is ready to be inspected.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John W. Ramey TITLE Production Superintendent DATE March 14, 1966

APPROVED BY John W. Ramey TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: