

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

1001 OFFICE C. C. C.
MAR 17 11 38 AM

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.
-

7. Unit Agreement Name
-

8. Farm or Lease Name
G. M. Whitmire

9. Well No.
1

10. Field and Pool, or Wildcat
Bronco-Devonian, West

11. Field and Pool, or Wildcat
Bronco-Devonian, West

12. County
Lea

13. Elevation (Show whether DF, RT, GR, etc.)
3857 - GL

14. County
Lea

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator Ashmun & Hilliard
3. Address of Operator 303 N. Marienfeld St., Midland, Texas 79701
4. Location of Well UNIT LETTER "J" 2310 FEET FROM THE South LINE AND 2310 FEET FROM THE East LINE, SECTION 6 TOWNSHIP 13-S RANGE 38-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3857 - GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Operator proposes to plug and abandon on March 13, 1966, at approximately 9:00 a.m.

Will shoot off and pull 8 5/8" casing. Plugs to be set as follows:

- 25 sx plug in top of stub of 8 5/8" casing
- 25 sx plug in base of surface pipe
- 10 sx plug in top of surface pipe
- 25 sx plug at TD 11,726'
- 25 sx plug at top of Penn 9800'
- 25 sx plug at top of Tubb 7285'
- 25 sx plug at top of Glorieta 5995'
- 25 sx plug at bottom of 8 5/8" casing 4865'

Mud will be applied between all plugs from TD back to surface.
Surface marker will be set in top of cement.
Location to be cleared.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Superintendent DATE March 14, 1966

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: