

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
JUL 28 2 48 PM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.
State - E-9247

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	NONE
3. Address of Operator	8. Farm or Lease Name
TEXACO Inc.	N. M. "DA" State NCT-1
4. Location of Well	9. Well No.
UNIT LETTER D, 810 FEET FROM THE West LINE AND 660 FEET FROM	1
THE North LINE, SECTION 14 TOWNSHIP 12-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat
	Ranger Lake (Penn)
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4166' (D. F.)	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	OTHER <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
OTHER <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to Temporarily Abandon subject well as of 7:00 A. M. August 1, 1967, and the following work has been completed as approved by the NMOC, Form C-103, dated May 26, 1967.

1. Pull pump equipment, set Cast Iron bridge Plug at 9900', dump 5 gallons hydromite on top of plug.
2. Perforate 2 7/8" O. D. Casing with one jet shot per foot from 9602' to 9608', and 9623' to 9632'.
3. Acidize perforations with 500 gallons 15% NEA acid. Swab well. No show. Shut well in.
4. Well Temporarily Abandoned, 7:00 A. M. August 1, 1967.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED	TITLE	DATE
J. G. Blevins, Jr.	Assistant District Supt.	July 28, 1967
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		