| So. indicate Type of Lease State K Foe Sta | O. OF COPIES RECEIVED | | Form C-103 |
|--|---|--|--|
| NEW MEXICO OIL CONSERVATION COMMISSION Effective 1-was NO.5. S. Since of Equation 1 | DISTRIBUTION | | |
| SUNDRY NOTICES AND REPORTS ON WELLS TO NOT SEE THIS TOTAL WORK THIS TOTAL PROPERTY OF PROPERTY OF THE PROPERT | NTAFE | NEW MEXICO OIL CONSERVATION COMMISSION | |
| SUNDRY NOTICES AND REPORTS ON WELLS OF NOTE: SUNDRY NOTICES AND REPORTS ON WELLS OF NOTE: SUNDRY NOTICES AND REPORTS ON WELLS OF NOTE: Renger Lake Unit 1. Derivation of Notice and Notice of | LE | | |
| SUNDRY NOTICES AND REPORTS ON WELLS ***CONTROL OF THE PROPERTY OF THE PROPERT | s.G.S. | | |
| SUNDRY NOTICES AND REPORTS ON WELLS Content Content | ND OFFICE | | |
| SUNDRY NOTICES AND REPORTS ON WELLS STATE STATE STATES AND REPORTS ON WELLS STATE STATES AND STATES AND REPORTS ON WELLS STATES AND STATES A | ERATOR | | |
| Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INT | | | E 1051-1 |
| Ranger Lake Unit S. Furner Lease Rome Ranger Lake Unit, Tract Ranger | SUNDA (DO NOT USE THIS FORM FOR PRI USE "APPLICAT | RY NOTICES AND REPORTS ON WELLS opposals to Orill or to Deepen or plug back to A Different reservoir. Tion for permit - " (form C-101) for such proposals.) | |
| Ranger Lake Unit, Tract direction of Checking South Page 1980 Test radius of Checking Notice of Notice of Notice of Notice of Notice, Report of Other Data Notice of Intention To: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data Notice of Intention To: Subsequent Report of: The Author Canada | OIL GAS WELL WELL | OTHER- | |
| S. Well No. 144 10. Field and Pool, or Wildcott Ranger Lake Penn 11. Committee Ranger Lake Penn 12. Sauch 13. Elevation (Show whether DF, RT, CR, etc.) 14. Lea 14. Subsequent Report of Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: 15. Elevation (Show whether DF, RT, CR, etc.) 16. Committee Ranger Lake Penn 16. Committee Ranger Lake Penn 17. Committee Ranger Lake Penn 18. Committee Ranger Lake Penn 19. Committee Ranger Lake Ranger Lake Penn 19. Committee Ranger Lake Ranger Lake Penn 19. Committee Ranger Lake Ranger Lake Ranger Lake Penn 19. Committee Ranger Lake Ra | ame of Operator Phillips Petroleum Co | ompany | 8. Form or Lease Name Ranger Lake Unit, Tract |
| Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: CHANGE PLANS CHANGE CHANGE CHANGE PLANS C | ddress of Operator | | 9. Well No. |
| Ranger Lake Penn 1980 1980 1980 1980 1980 1980 1980 1980 1980 1980 1980 1980 1980 1980 1980 198 | | ldg., Odessa, Texas 79760 | |
| The west Line, Section 23 Township 12-8 Range 34-E NAMES. 13. Cleavellen (Show whether DF, RT, GR, etc.) 12. County 14149 Gr. 12. County 14149 Gr. | | 1980 south 1980 | ' |
| Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TORM MEMBEDIAL WORK NOTICE OF INTENTION TO: TORM MEMBEDIAL WORK SUBSEQUENT REPORT OF: TORM MEMBEDIAL WORK COMMETTED FORDSHIP OF THE STAND CEMENT JOB OTHER STREET Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed owney) see Rulle 1103. P-1-71: MI Lovington WS unit, pulled and reset tbg in pkr at 10196'. MO unit 9-8-71, MI Casir Fullers Inc. Pumped in csg perfs 10224-10326' below pkr. Pulled bg out of pkr. Displaced tbg and csg w/mmd laden fluid. Mixed 50 sx Class H cmt, pumped 10 sx below packer, left 40 sx in csg above pkr. Pulled tbg. Tested csg w/500#, OK. Welded collar on 4-1/2"csg. 9-9-10/11-71: Shot and pulled 145 jts (4720') 4-1/2" csg. Casing cat at 4/20'. Ran 2-3/8" tbg, spotted 30 sx from 4770' to 1670'. Pulled tbg, spotted 35 sx cmt 4250' to 4150'. Pulled tbg. 9-12-71. Shot well of 13-3/8" and 8-5/8" csg free at 700'. Shot 8-5/8" collars at 2000', 1500', 1250', and 799'. Pulled 25 jts, 799', 8-5/8" csg. Ran 2-3/8" tbg, spotted 60 ax cmt 850-750'. Spotted 100 ax cement from 400' to 310', 10 sx cmt from 30' to surface. Installed dry hole marker. Well P&A 1 | | 23 12_9 3/_F | |
| Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: SUBSEQUENT REPORD | THE LINE, SECTI | 10N TOWNSHIP RANGE | NMPM. ((((()))) |
| Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SUBSICION SUBSEQUENT REPORT | | | |
| NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PRIME AND ABANDON | | 4149' Gr. | Lea |
| PLUG AND ABANDON PLUG AND ABANDONMENT | | | |
| COMMENCE OFFICING OPENS. CHANGE PLANS CHAN | NOTICE OF I | NTENTION TO: SUBSEQUE | UENT REPORT OF: |
| COMMENCE OFFICING OPENS. CHANGE PLANS CHAN | | | |
| CHANGE PLANS CH | Ħ | <u> </u> | f |
| Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see mule 1103. 9-7-71: MI Lovington WS unit, pulled and reset tbg in pkr at 10196'. MO unit 9-8-71, MI Casir Fullers Inc. Pumped in csg perfs 10224-10326' below pkr. Pulled tbg out of pkr. Displaced tbg and csg w/mmd laden fluid. Mixed 50 sx Class H cmt, pumped 10 sx below packer, left 40 sx in csg above pkr. Pulled tbg. Tested csg w/500#, OK. Welded collar on 4-1/2"csg. 9-9/10/11-71: Shot and pulled 145 jts (4720') 4-1/2" csg. Casing cut at 4720'. Ran 2-3/8" tbg, spotted 30 sx from 4770' to 4670'. Pulled tbg, spotted 35 sx cmt 4250' to 4150'. Pulled tbg. 9-12-71. SD. 9-12-71: Cut off 13-3/8" and 8-5/8" csghead. Welded collar on 8-5/8" csg. Stretch showed 8-5/8" csg free at 700'. Shot 8-5/8" collars at 2000', 1500', 1250', and 799'. Pulled 25 jts, 799', 8-5/8" csg. Ran 2-3/8" tbg, spotted 60 sx cmt 850-750'. Spotted 100 sx cement from 400' to 310', 10 sx cmt from 30' to surface. Installed dry hole marker. Well PkA 9-13-71. | Ħ | | PLUG AND ABANDONMENT |
| Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 9-7-71: MI Lovington WS unit, pulled and reset tbg in pkr at 10196'. MO unit 9-8-71, MI Casir Pullers Inc. Pumped in csg perfs 10224-10326' below pkr. Pulled tbg out of pkr. Displaced tbg and csg w/mud laden fluid. Mixed 50 sx Class H cmt, pumped 10 sx below packer, left 40 sx in csg above pkr. Pulled tbg. Tested csg w/500#, OK. Welded collar on 4-1/2"csg. 9-9/10/11-71: Shot and pulled 145 jts (4720') 4-1/2" csg. Casing cut at 4720'. Ran 2-3/8" tbg, spotted 30 sx from 4770' to 4670'. Pulled tbg, spotted 35 sx cmt 4250' to 4150'. Pulled tbg. 9-12-71. SD. 9-13-71: Cut off 13-3/8" and 8-5/8" csghead. Welded collar on 8-5/8" csg Stretch showed 8-5/8" csg free at 700'. Shot 8-5/8" collars at 2000', 1500', 1250', and 799'. Bulled 25 jts, 799', 8-5/8" csg. Ran 2-3/8" tbg, spotted 60 sx cmt 850-750'. Spotted 100 sx cement from 400' to 310', 10 sx cmt from 30' to surface. Installed dry hole marker. Well RAA 9-13-71. | OR ALTER CASING | | |
| Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 9-7-71: MI Lovington WS unit, pulled and reset tbg in pkr at 10196'. MO unit 9-8-71, MI Casir Pullers Inc. Pumped in csg perfs 10224-10326' below pkr. Pulled tbg out of pkr. Displaced tbg and csg w/mud laden fluid. Mixed 50 sx Class H cmt, pumped 10 sx below packer, left 40 sx in csg above pkr. Pulled tbg. Tested csg w/500#, OK. Welded collar on 4-1/2"csg. 9-9/10/11-71: Shot and pulled 145 jts (4720') 4-1/2" csg. Casing cut at 4720'. Ran 2-3/8" tbg, spotted 30 sx from 4770' to 4670'. Pulled tbg, spotted 35 sx cmt 4250' to 4150'. Pulled tbg. 9-12-71. SD. 9-13-71: Cut off 13-3/8" and 8-5/8" csghead. Welded collar on 8-5/8" csg Stretch showed 8-5/8" csg free at 700'. Shot 8-5/8" collars at 2000', 1500', 1250', and 799'. Pulled 25 jts, 799', 8-5/8" csg. Ran 2-3/8" tbg, spotted 60 sx cmt 850-750'. Spotted 100 sx cement from 400' to 310', 10 sx cmt from 30' to surface. Installed dry hole marker. Well P&A 9-13-71. | | | |
| 9-7-71: MI Lovington WS unit, pulled and reset tbg in pkr at 10196'. MO unit 9-8-71, MI Casir Pullers Inc. Pumped in cag perfs 10224-10326' below pkr. Pulled tbg out of pkr. Displaced tbg and csg w/mud laden fluid. Mixed 50 sx Class H cmt, pumped 10 sx below packer, left 40 sx in csg above pkr. Pulled tbg. Tested csg w/500#, OK. Welded collar on 4-1/2"csg. 9-9/10/11-71: Shot and pulled 145 jts (4720') 4-1/2" csg. Casing cut at 4720'. Ran 2-3/8" tbg, spotted 30 sx from 4770' to 4670'. Pulled tbg, spotted 35 sx cmt 4250' to 4150'. Pulled tbg. 9-12-71. SD. 9-13-71: Cut off 13-3/8" and 8-5/8" csghead. Welded collar on 8-5/8" csg Stretch showed 8-5/8" csg free at 700'. Shot 8-5/8" collars at 2000', 1500', 1250', and 799'. Pulled 25 jts, 799', 8-5/8" csg. Ran 2-3/8" tbg, spotted 60 sx cmt 850-750'. Spotted 100 sx cement from 400' to 310', 10 sx cmt from 30' to surface. Installed dry hole marker. Well PkA 9-13-71. M.J. Mueller Title Semior Reservoir Engineer Date 9-15-71 | | OTHER | |
| W.J. Mueller TITLE Senior Reservoir Engineer DATE 9-15-71 | Describe Proposed or Completed Op | | luding estimated date of starting any proposed |
| W.J. Mueller TITLE Senior Reservoir Engineer DATE 9-15-71 | 9-7-71: MI Lovington Pullers Inc. Pumped tbg and csg w/mud lac in csg above pkr. Ptg-9/10/11-71: Shot atbg, spotted 30 sx fitbg. 9-12-71. SD. Stretch showed 8-5/8' Pulled 25 jts, 799', cement from 400' to 3 | n WS unit, pulled and reset tbg in pkr at 101 in csg perfs 10224-10326' below pkr. Pulled den fluid. Mixed 50 sx Class H cmt, pumped 1 ulled tbg. Tested csg w/500#, OK. Welded co and pulled 145 jts (4720') 4-1/2" csg. Casir rom 4770' to 4670'. Pulled tbg, spotted 35 s 9-13-71: Cut off 13-3/8" and 8-5/8" csghead "csg free at 700'. Shot 8-5/8" collars at 2 8-5/8" csg. Ran 2-3/8" tbg, spotted 60 sx collars. | 196'. MO unit 9-8-71, MI Casi it bg out of pkr. Displaced to sx below packer, left 40 sx belar on 4-1/2"cag. Ing cut at 4720'. Ran 2-3/8" is cmt 4250' to 4150'. Pulled it. Welded collar on 8-5/8" cs 2000', 1500', 1250', and 799'. Emt 850-750'. Spotted 100 sx |
| | Describe Proposed or Completed Onwork) SEE RULE 1103. 9-7-71: MI Lovington Pullers Inc. Pumped tbg and csg w/mud law in csg above pkr. Ptg-9/10/11-71: Shot atbg, spotted 30 sx fitbg. 9-12-71. SD. Stretch showed 8-5/8' Pulled 25 jts, 799', cement from 400' to 39-13-71. | operations (Clearly state all pertinent details, and give pertinent dates, income makes the state of the stat | 196'. MO unit 9-8-71, MI Casing the distribution of pkr. Displaced to sx below packer, left 40 sx belar on 4-1/2"csg. In grant at 4720'. Ran 2-3/8" sx cmt 4250' to 4150'. Pulled to Welded collar on 8-5/8" csg 2000', 1500', 1250', and 799'. In the state of the sta |
| | Describe Proposed or Completed Onwork) SEE RULE 1103. 9-7-71: MI Lovington Pullers Inc. Pumped tbg and csg w/mud law in csg above pkr. Ptg-9/10/11-71: Shot atbg, spotted 30 sx fitbg. 9-12-71. SD. Stretch showed 8-5/8' Pulled 25 jts, 799', cement from 400' to 39-13-71. | operations (Clearly state all pertinent details, and give pertinent dates, income makes the state of the stat | 196'. MO unit 9-8-71, MI Casir it to the out of pkr. Displaced to sx below packer, left 40 sx belar on 4-1/2"csg. In grut at 4720'. Ran 2-3/8" is cmt 4250' to 4150'. Pulled it. Welded collar on 8-5/8" csg 2000', 1500', 1250', and 799'. Emt 850-750'. Spotted 100 sx |
| WHE OLD OUR GAS INSPECTION | Describe Proposed or Completed Onwork) SEE RULE 1103. 9-7-71: MI Lovington Pullers Inc. Pumped tbg and csg w/mud law in csg above pkr. Ptg-9/10/11-71: Shot atbg, spotted 30 sx fitbg. 9-12-71. SD. Stretch showed 8-5/8' Pulled 25 jts, 799', cement from 400' to 39-13-71. | operations (Clearly state all pertinent details, and give pertinent dates, income makes the state of the performance of the control of the co | 196'. MO unit 9-8-71, MI Casing the distributed the second of pkr. Displaced to sx below packer, left 40 sx caller on 4-1/2"csg. In great at 4720'. Ran 2-3/8" sx cmt 4250' to 4150'. Pulled to Welded collar on 8-5/8" csg 2000', 1500', 1250', and 799'. cmt 850-750'. Spotted 100 sx led dry hole marker. Well P&A |
| OT S GAS INSPECTACE LABORATION | P-7-71: MI Lovington Pullers Inc. Pumped tbg and csg w/mud lac in csg above pkr. Ptg-9/10/11-71: Shot atbg, spotted 30 sx fitbg. 9-12-71. SD. Stretch showed 8-5/8' Pulled 25 jts, 799', cement from 400' to 39-13-71. | operations (Clearly state all pertinent details, and give pertinent dates, income makes the state of the performance of the control of the co | 196'. MO unit 9-8-71, MI Casing the distributed the second of pkr. Displaced to sx below packer, left 40 sx caller on 4-1/2"csg. In great at 4720'. Ran 2-3/8" sx cmt 4250' to 4150'. Pulled to Welded collar on 8-5/8" csg 2000', 1500', 1250', and 799'. cmt 850-750'. Spotted 100 sx led dry hole marker. Well P&A |
| | Pescribe Proposed or Completed Onwork) SEE RULE 1103. 9-7-71: MI Lovington Pullers Inc. Pumped tbg and csg w/mud law in csg above pkr. Ptg-9/10/11-71: Shot atbg, spotted 30 sx fitbg. 9-12-71. SD. Stretch showed 8-5/8' Pulled 25 jts, 799', cement from 400' to 39-13-71. | operations (Clearly state all pertinent details, and give pertinent dates, incoming the state of the lates of | 196'. MO unit 9-8-71, MI Casing the distribution of pkr. Displaced to sx below packer, left 40 sx collar on 4-1/2"csg. Ran 2-3/8" ex cmt 4250' to 4150'. Pulled i. Welded collar on 8-5/8" csg 2000', 1500', 1250', and 799'. Cmt 850-750'. Spotted 100 sx led dry hole marker. Well P&A |

RHUNIVED

SUF 17 1971

OIL CORSET ATTOM COUNT,