

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-11068	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Charles B. Gillespie, Jr.	State
3. Address of Operator	9. Well No.
P. O. Box 1179 Midland, Texas, 79701	2
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>E</u> <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>990'</u> FEET FROM	<u>Lazy J</u>
THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>13-S</u> RANGE <u>33-E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4222 DF	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) 50 sx cement plug set across perforations 9728-32 and 9740-43.
- 2.) 4 1/2" casing will be shot off and pulled from 7200'.
- 3.) 25 sx cement plug will be set across 4 1/2" casing stub.
- 4.) 25 sx cement plug will be set at base of intermediate casing at 4150'.
- 5.) 8 5/8" casing will be shot off and pulled from 2200'.
- 6.) 25 sx cement plug will be set across 8 5/8" casing stub.
- 7.) 10 sx cement plug will be set at base of surface casing at 346'.
- 8.) 10 sx cement plug will be set at top of surface pipe with 4" marker pipe 4' above surface.
- 9.) All intervals between plugs will be filled with mud.
- 10.) Location will be levelled and cleaned.
- 11.) Work will commence after approval depending on rig availability.

25 sxs Top Glorietta
25 sxs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Charles B. Gillespie, Jr.</u>	TITLE <u>Operator</u>	DATE <u>1-8-69</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>[Signature]</u>	DATE <u>[Signature]</u>
CONDITIONS OF APPROVAL, IF ANY:		