

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-21923
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VA-5
7. Lease Name or Unit Agreement Name Ranger AHJ State
8. Well No. 1
9. Pool name or Wildcat <i>Nacimiento Upper Penn</i>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4157.6' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> RE-ENTRY <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION	3. Address of Operator 105 South 4th St., Artesia, NM 88210
4. Well Location Unit Letter <u>F</u> : <u>2080</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>32</u> Township <u>13S</u> Range <u>34E</u> NMPM <u>Lea</u> County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4157.6' GR		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Repair, Perforate, Treat <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-5-90. Pull tubing and laid down 56 jts - 10th joint above packer was collapsed. Picked up 3-hole sand drill tool and 56 jts new tubing and TIH. Made 1 - 10 minute cut @ 10662'. Reversed clean. Spot 33 bbls. Loaded tubing and pressure tubing.
4-9-90. Respot 250 gals 28% NEFE acid. Repressure tubing to a maximum of 6000 psi in different stages.
4-11-90. Made 3-hole cut at 10683'. Spot 200 gals 20% NEFE acid. Pressure tubing to 3000 psi. No bleed off. SI.
4-12-90. Repressure to 4000 psi with no bleed off. Perforated 12 - .32" holes as follows: 10653' (4 holes), 10662-64' (4 holes) and 10683-84' (4 holes) with acid spotted at 2000 psi on tubing.
4-14-90. Swabbed 85 bbls water. No shows.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 4-17-90

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APR 19 1990

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: