

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-21923
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VA-5
7. Lease Name or Unit Agreement Name Ranger AHJ State
8. Well No. 1
9. Pool name or Wildcat Nonombre Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER ☐ P&A WELL

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter F : 2080 Feet From The North Line and 1980 Feet From The West Line

Section 32 Township 13S Range 34E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4157.6' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

page 2 - continued) POH and laid down 45 joints tubing to 4325'. Mixed and pumped 25 sx Class "C" cement and displaced with 21.5 BMLF. POH and stand back 20 joints tubing. Cleared tubing. POH and stand back another 30 joints tubing. WOC. RIH w/126.5 joints tubing and tagged TOC at 4085'. POOH and laid down 47 joints tubing to 2552'. Loaded hole. Mixed and pumped 25 sx Class "C" cement and displaced with 11 BMLF. POOH and laid down 67 joints tubing to 387'. Loaded hole. Mixed and pumped 40~sx Class "C" cement to circulate cement to surface in 5-1/2" casing. Cleaned and flushed lines and BOP. Rigged down. Cut off wellhead and install dry hole marker.
Work began 3-5-93. - plugging completed 3-14-93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 3-29-93
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Jack Griffin TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAR 30 1993
OCD HOBBS OFFICE

RECEIVED
MAR 30 1993
OCD HOBBS OFFICE