

## O CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K-3909

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Rapid Company, Inc.	8. Farm or Lease Name Ranger Lake
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 755, Hobbs, New Mexico 88240	9. Well No. 3
4. Location of Well UNIT LETTER <u>W</u> <u>557</u> FEET FROM THE <u>South</u> LINE AND <u>1917</u> FEET FROM THE <u>West</u> LINE, SECTION <u>11</u> TOWNSHIP <u>12S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Wildcat Ranger Lake - SA
15. Elevation (Show whether DF, RT, GR, etc.) 4167	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug &amp; abandon as follows:

Set cast iron bridge plug at 4800 & cap with 5 sacks cement  
 Spot 100' plug in 4 1/2" casing opposite top of salt as 2100  
 10 sack plug at surface with regulation marker  
 Mud between all plugs

WILL HAVE TO PULL 4 1/2" OR PERFE SQ W/ CEMENT  
 ABOVE TOP OF SALT  
 OJA RECORDS SHOW TOC @ 2400'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Donna Hales</u>	TITLE <u>Agent</u>	DATE <u>8/7/85</u>
APPROVED BY <u>ORIGINAL SIGNATURE OF DIVISION</u>	TITLE <u></u>	DATE <u>1985</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

AUG -8 1985

QCA  
HUMAN RIGHTS