

**DISTRICT I**  
P.O. Box 1980, Hobbs, NM 88240  
**DISTRICT II**  
P.O. Box Drawer DD, Artesia, NM 88210  
**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 22020
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-9560
7. Lease Name or Unit Agreement Name	NEW MEXICO BG STATE NCT 1
8. Well No.	4
9. Pool Name or Wildcat	SAUNDERS PERMO UPPER PENN
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4212 DF

**SUNDRY NOTICES AND REPORTS ON WELL**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	P.O. BOX 730, HOBBS, NM 88240
4. Well Location	Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>14</u> Township <u>14S</u> Range <u>33E</u> NMPM <u>LEA</u> COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	REQUEST TA STATUS <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  
3/22/94 - 3/25/94

- TOH W/ PRODUCTION EQUIPMENT.
- SET CIBP @ 9720' & CAP W/ 35' CMT.
- CIRC PKR FL FROM 9500 TO SURFACE, TRY TO PRESS TEST, LEAKING OFF 500 TO 420 IN 30 MIN.
- PRESSURE TEST CSG TO 960# LEAKED OFF TO 825# IN 30 MIN., WITNESSED BY BUDDY HILL. TEST PASSED VIA PHONE CONVERSATION WITH JERRY SEXTON
- TOH W/ TBG. REQUEST TEMPORARILY ABANDONED WELL STATUS THROUGH 3/1/99.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.


SIGNATURE Darrell J. Carriger TITLE Engineering Assistant DATE 3/30/94

TYPE OR PRINT NAME Darrell J. Carriger Telephone No. 397-0431

(This space for State Use)

APPROVED BY JERRY SEXTON TITLE DISTRICT I SUPERVISOR DATE APR 01 1994

This Approval of Temporary Abandonment Expires 3-1-99



RECEIVED

MAR 31 1934

Q. 1026

PRINTED IN U. S. A.

TEXACO EXPLORATION AND PRODUCTION INC

HOBBS NEW MEXICO 86241-0730

E 19, 145, 33E

Lee Corbett N.M.

TEJAS  
INSTRUMENT ENGINEERS

3/25/74

N.M. BG Nct-1 #4

WATER METER  
WIRE PUT ON  
WIRE PUT ON

WIRE & METER  
TIME TAKEN OFF  
WIRE TAKEN OFF

BR-2221  
B 0-1000-8

B.H. Hall

Start

DAY

NIGHT