

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

APR 17 3 24 AM '67

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-6639
7. Unit Agreement Name *****
8. Farm or Lease Name Hobbs "Y"
9. Well No. 1
10. Field and Pool, or Wildcat undesignated
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Skelly Oil Company
3. Address of Operator P.O. Box 730, Hobbs, New Mexico
4. Location of Well UNIT LETTER J , 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 29 TOWNSHIP 12S RANGE 34E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4197' RT

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was drilled to a total depth of 10,397' in lime and with no commercial quantities of oil or gas encountered in any zone. We now plan to plug and abandon this well in the following manner:

1. Run free point indicator on 8-5/8" CD casing.
2. Cut and pull 8-5/8" CD casing from approximately 2300'.
3. Spot cement plugs through open ended drill pipe at the following depths:

10,397-10,234'	- 30 sacks cement
9,300- 9,219'	- 25 sacks cement
7,700- 9,619'	- 25 sacks cement
3,600 - 3,519'	- 25 sacks cement
4,235- 4,155'	- 25 sacks cement - 8-5/8" CD casing set at 4195'
2,470- 2,530'	- 25 sacks cement in and out of 8-5/8" stub.
2,000- 1,959'	- 25 sacks cement
414- 376'	- 25 sacks cement - 11-3/4" CD casing set at 414'.
4. Place 10 sack cement cap in top of 11-3/4" CD casing and install 4" steel dry hole marker.
5. All intervals not cemented will be filled with heavy mud laden fluid.

Mr. Joe D. Ramsey of the New Mexico Oil Conservation gave verbal approval on April 13, 1967 to plug and abandon this well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **(ORIGINAL SIGNED) V. E. Fletcher** TITLE **District Superintendent** DATE **April 14, 1967**

APPROVED BY **Joe D. Ramsey** TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: