DISTRIBUTION				Form C-103
CANTA EE				Supersedes Old C-102 and C-103
SANTAFE		NEW MEX	ICO OIL KONSERVATION COMMISSION	Effective 1-1-65
FILE				
U.S.G.S.	\longrightarrow		MAR II 1 25 PH '67	State Fee.
LAND OFFICE			•••	5. State Oil & Gas Lease No.
OPERATOR				K-6639
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				
l.	GAS			7. Unit Agreement Name
WELL	WELL	OTHER-		8. Farm or Lease Name
@1		11 Company		Hobbs 11911
3. Address of Operator	celly G			9. Well No.
D .4		130, Hobbs, How 1	leries	1
4. Location of Well				10. Field and Pool, or Wildcat
UNIT LETTER	.	1980 FEET FROM 1	HE South LINE AND 1989 FEET F	FROM Underignated
		- 		
THE East	LINE, SE	CTION TOV	VNSHIP 128 RANGE 348 N	MPM. (
	*****		DD DD CD	
		15. Elevatio	on (Show whether DF, RT, GR, etc.)	12. County
ŽIIIIIII.			4197' DF	Les
. N.		k Appropriate Box 1	To Indicate Nature of Notice, Report or SUBSEQU	Other Data ENT REPORT OF:
			_	
PERFORM REMEDIAL WOR	к 🔙	PLUG A	ND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CHANGE	E PLANS CASING TEST AND CEMENT JOB	
			OTHER	
17. Describe Proposed work) SEE RULE 1	or Completed	d Operations (Clearly state	all pertinent details, and give pertinent dates, inclu	uding estimated date of starting any proposed
17. Describe Proposed work) SEE RULE 1 Reached dep 324, a tota 600 sacks of Temperature 24 hours	th of 4: 1 of 13: 6 censes survey Tosted	195' March 8, 19 0 joints (4182') t by the pump an indicated comm essing to 10000		end 71 joints (2309') ing at 4195'. Commtod wi :45 A.M. March 9, 1967. 41' from surface. WGG
17. Describe Proposed work) SEE RULE 1 Reached dep 326, a tota 630 sacks of Temperature 24 hours. casing to 6	th of 4: 1 of 13: 2 census 2 census 3 census 3 census 3 census 4 census 4 census 5 census 6 c	195' March 8, 19 0 joints (4182') t by the pump an indicated comm casing to 10000 30 minutes and	all pertinent details, and give pertinent dates, included. 67. Set 39 joints (1873') 244 of new 82 88 J-35 R-2 8766 casts deplay process. Flug down at 3 toutside 8-5/8"60 casing at 25 for 36 minutes and tested 6K. casing shat off tested 6K.	end 71 joints (2909') ing at 4195'. Comented wit :45 A.M. Merch 9, 1967. 41' from surface. WGC Brilled plug and tested
17. Describe Proposed work) SEE RULE 1 Reached dep 326, a total (68 sacks of Tumpersture 24 hours. casing to 6	th of 4: 1 of 13: 6 cenes: auxvey Tested: 60f for	195' March 8, 19 0 joints (4182') t by the pump an indicated comme easing to 10000 30 minutes and	all pertinent details, and give pertinent dates, included. 57. Set 59 joints (1873') 244 of new 82 58 J-55 R-2 5766 casis of plug process. Plug down at 3 toutoide 8-5/8"00 casing at 25 for 36 minutes and tested 6K. casing shut off tested 6K.	end 71 joints (2309') ing at 4195'. Commated with 145 A.M. Merch 9, 1967. 41' from surface. WGC Brilled plug and tested

CONDITIONS OF APPROVAL, IF ANY: