

Tatum (Wolfcamp) Field
Turner Well No. 1
Lea County, New Mexico

Plug & Abandon

12-18-89-MIRU Pool WS DDPU.

12-19-89-Rel tbg anchor & TOH w/tbg. Ran & set 5 1/2" cmt ret @ 10,000' on WL. Ran cmt stinger on 2 3/8" & 2 7/8" tbg to 9700'.

12-21-89-Disp hole w/250 bbl 10# mud laden fluid & est inj rate of 2 BPM & 2000# into Wolfcamp perfs 10,283-10,315'. Sqz'd perfs w/50 sxs Cl "H" cmt. Pres to 2000# @ 1/2 BPM. Sptd 6 1/2 bbl cmt on ret (PLUG #1-9725-10,315').

12-26-89-Cut 5 1/2" csg @ 6400'. Lay dn 98 jts & 2 pcs of 5 1/2".

12-27-89-Spot 25 sxs Cl "C" cmt frm 7400-7148' (PLUG #2). PU to 6450'. Spot 45 sxs Cl cmt frm 6450-6244' (PLUG #3). PU to 5250', WOC.

12-28-89-RIH w/2 7/8" tbg open ended, tag TOC @ 6352'. Spot 65 sxs Cl "C" frm 5950-5697' (PLUG #4). Spot 65 sxs Cl "C" cmt frm 4495-4249' (PLUG #5). WOC 4 hrs. TIH w/2 7/8" tbg, tag TOC @ 4340'. Spot 45 sxs Cl "C" cmt frm 3100-2927' (PLUG #6).

12-29-89-Sptd 100 sxs Cl "C" cmt frm 2180-1811' (PLUG #7). PU on 8 5/8" csg & work same. Est free pt by stretch @ 588'. Shoot csg @ 534' & work same free. POH & LD 15 jts & 2 pcs 8 5/8". Sptd 65 sxs Cl "C" cmt frm 584-455' (PLUG #8). POH & WOC.

12-30-89-RIH w/oe'd 2 7/8" tbg & tag TOC @ 418'. Sptd 100 sxs Cl "C" 377-177' (PLUG #9). TOH & WOC 4 hrs. RIH w/oe'd 2 7/8" tbg & tag TOC @ 222'. Sptd 15 sxs Cl "C" frm 40'-surf (PLUG #10). Cut off csg hd & weld on P&A marker. RD&MODDPU. Well P&A'ed 12-30-89.