

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-22111

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Childress AKV

8. Well No.

2

9. Pool name or Wildcat Lazy J
~~Saunders Permo Upper Penn~~

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

4. Well Location

Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line

Section

1

Township

14S

Range

33E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4196' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Clean out hole ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-24-94 - TIH w/4-1/2" cutrite shoe with 3' extension, jars, collars and tubing. Tag junk at 8912'. Cut 45 minutes. Made 2' and junk fell down hole. Pushed down to packer at 9813'. Mill 2 hours and made 1'. Circulate clean and TOOH. Shoe worn out. Shut in.

8-25-94 - TIH w/4-1/2" cutrite shoe with 3' extension, jars, drill collars and tubing. Tag packer at 9813'. Made 1-1/2' in 4 hours. Quit torqueing. TOOH - shoe worn out. TIH with 4-1/2" cutrite shoe with 4' extension, jars, drill collars and tubing. Started cutting at 5:30 PM. Swivel locked up at 7:00 PM. Broke off swivel with top joint and laid down. Shut down.

8-26-94 - Picked up 3-1/2" swivel. Tagged at 9816'. Rotated 20 minutes. Rotated over 4'. No torque to 9820'. Milled 1-1/2' to 9821.5' in 1-1/2 hours - did not make any hole. TOOH with shoe. TIH with 4-1/2" shoe with 2 extensions to swallow 10'. Tag at 9821.5'. Cut 2' - cement and metal shavings in returns. Circulate clean. Picked up off bottom 15'. Shut in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Rusty Klein

TITLE

Production Clerk

DATE 9-6-94

TYPE OR PRINT NAME

Rusty Klein

505-748-1471
TELEPHONE NO.

SEP 12 1994

(This space for State Use)

APPROVED BY

TITLE

DATE