

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-22111
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Childress AKV
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 2
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	9. Pool name or Wildcat <u>Levy</u> <u>Saunders Permo Upper Penn</u>
4. Well Location Unit Letter <u>L</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>1</u> Township <u>14S</u> Range <u>33E</u> NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4196' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Re-entry</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-14-94 - Recovered cup full of iron chunks. TIH with magnet. Tag at 3950'. TOOH. Recovered handful of slivers. TIH with new 7-7/8" bit. Tagged at 3850'. Started drilling. Drilled thru shoe plug. Fell out of cement at 4210'. Washed down. Tagged cement plug at 5528'. Fell out of cement at 5550'. Washed down to 5745'.

8-15-94 - Washed down to 5745'. Tagged shoe plug at 6535'. Drilled cement to 6596'. Bit locked up. TOOH. Changed bits. TIH with 7-7/8" retip bit. Drilled 6' to 6602'. Tagged top of sub. Circulated clean. TOOH. TIH w/4-3/4" bit, 3-1/2" drill collars and 7-5/8" dress off mill, jars, drill collar and tubing. Tagged 5-1/2" sub. Drilled down 27'. Dressed off top of sub. Dressed off 5-1/2". Circulated. TOOH.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 8-16-94
TYPE OR PRINT NAME Rusty Klein 505-748-1471
TELEPHONE NO.

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE AUG 18 1994

RECEIVED

APR 17 1964

ADJUTANT
GENERAL
OFFICE