

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|   |
|---|
| WELL API NO.<br>30-025-22111  |
| 5. Indicate Type of Lease<br>STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No.  |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|   |   |
|---|---|
| 1. Type of Well:<br>Oil Well <input checked="" type="checkbox"/> GAS Well <input type="checkbox"/> OTHER <input type="checkbox"/>   | 7. Lease Name or Unit Agreement Name<br>Childress AKV                         |
| 2. Name of Operator<br>YATES PETROLEUM CORPORATION  | 8. Well No.<br>2  |
| 3. Address of Operator<br>105 South Fourth Street - Artesia, NM 88210   | 9. Pool name or Wildcat<br><del>Saunders Permo</del> <u>Lazy J</u> Upper Penn |
| 4. Well Location<br>Unit Letter <u>L</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line<br>Section <u>1</u> Township <u>14S</u> Range <u>33E</u> NMPM Lea County | 10. Elevation (Show whether DF, RKB, RT, GR, etc.)<br>4196' DF                |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO:                        |   | SUBSEQUENT REPORT OF:                                      |   |
|--|---|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>                     | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input type="checkbox"/>           | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  |   | CASING TEST AND CEMENT JOB <input type="checkbox"/>        |   |
| OTHER: <input type="checkbox"/>                |   | OTHER: <u>Re-entry</u> <input checked="" type="checkbox"/> |   |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-12-94 - TOOH with 7-7/8" bit. Recovered 3 pieces of iron in cone. Bit in good shape. TIH with 7-5/8" magnet, 10 4-3/4" drill collars and 2-7/8" tubing. Tagged junk. Rotated for 10 minutes. TOOH with magnet. Recovered 1 piece of iron and a handful of cuttings. TIH with 7-7/8" bit with drill collars and tubing. Tagged junk at 3905'. Drilled and pushed junk down. Circulated cement. Drilled to 3942'. Circulated clean. TOOH with bit. Two pieces of iron wedged in bit. Bit wore out. Cut full of metal pieces in junk basket. TIH w/7-7/8" shoe with wires and diamonds. Set down splice at 1245'. Could not get into stub. TOOH. TIH with 7-7/8" tapered mill. Reamed out top of stub. TOOH. TIH with 7-5/8" shoe. Tagged top of stub. Rotated 3/4 around. WIH. Tagged junk at 3942'. Started milling. Cut 1' to 3943'. Corking and sticking. Circulated hole.  
8-13-94 - TOOH with 7-7/8" shoe. TIH with 7" magnet, jars, 1 stand drill collar and tubing. Tagged junk. Rotated. TOOH. Recovered cup of slivers. TIH with 7-5/8" cone buster mill. Tagged junk. Started cutting. Cut 1-1/2' to 3944'. first hour. Did not make hole for 3 hours. TOOH with mill. TIH with 6-1/4" OD cutrite shoe with jars, collars and tubing. Tagged junk. Mill & cut to 3950'. TOOH. Recovered cement core & pieces of junk iron in shoe. TIH w/7" magnet. Circulate and rotate TOOH.  
I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 8-16-94  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY

TITLE

DATE

AUG 18 1994