NO. OF COPIES RECEIVED		Form C-103
i l	-	Supersedes Old
DISTRIBUTION	THE WENT OF CONCEDNATION COMMISSION	C-102 and C-103 Effective 1-1-65
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	Fueduve 1-1-03
FILE		5a, Indicate Type of Lease
U.S.G.S.		State Fee T
AND OFFICE		5. State Oil & Gas Lease No.
OPERATOR		9, 5, 5, 5, 5
\$1 INI	DRY NOTICES AND REPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. (DO NOT USE THIS FOR PROPOSALS.)		7. Unit Agreement Name
OIL GAS WELL	OTHER-	8, Farm or Lease Name
Name of Operator	1 Company	Childress "A"
. Address of Operator		9. Well No.
	Hobbs, New Mexico	10. Field and Pool, or Wildcat
. Location of Well	1980 FEET FROM THE South LINE AND 660 FEET FR	
UNIT LETTER		
THE West LINE, SE	CTION 1 TOWNSHIP 148 RANGE 338 NM	PM. (
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
16. Chec	k Appropriate Box To Indicate Nature of Notice, Report or	
	FINTENTION TO: SUBSEQUE	ENT REPORT OF:
		ALTERNO SAGNIC
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
		PLUG AND ABANDONMENT
	COMMENCE DRILLING OPNS.	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB	
TEMPORARILY ABANDON PULL OR ALTER CASING	COMMENCE DRILLING OPNS.	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Complete work) SEE RULE 1103.	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER d Operations (Clearly state all pertinent details, and give pertinent dates, included)	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Complete work) SEE RULE 1103. Well spudded May 6 casing at 374 and Plug down 6:45 P.M. Tested 11-3/4 GD 6	COMMENCE DRILLING OPNS. CHANGE PLANS OTHER OTHER	ding estimated date of starting any proposed 20f Armco SW SJ R-3 pump and plug process. 1. WCC 24 hours.
Pull or alter casing OTHER 17. Describe Proposed or Complete work) SEE RULE 1103. Well spudded May 6 casing at 374 and Plug down 6:45 P.M. Tested 11-3/4 GD c	commence drilling opns. casing test and cement Job other d Operations (Clearly state all pertinent details, and give pertinent dates, included, 1967. Set 9 joints (360°) of new 11-3/4°CD 31 cemented with 400 sacks regular cement by the 18. May 6, 1967. Cement Circulated to the surface casing up to 600° for 30 minutes and tested CK.	ding estimated date of starting any proposed 20f Armco SW SJ R-3 pump and plug process. 1. WCC 24 hours.
PULL OR ALTER CASING OTHER 17. Describe Proposed or Complete work) SEE RULE 1103. Well spudded May 6 casing at 374' and Plug down 6:45 P.M. Tested 11-3/4"GD c tested 11-3/4"GD c ORIGINAL	commence drilling opns. casing test and cement job other deperations (Clearly state all pertinent details, and give pertinent dates, included). 1967. Set 9 joints (360°) of new 11-3/4°69 31 commented with 400 sacks regular coment by the plants of the surface assing up to 600° for 30 minutes and tested CK. assing to 600° and casing shut off tested CK.	ding estimated date of starting any proposed 1.20f Armco SW SJ R-3 pump and plug process. 1. WOC 24 hours. Brilled plug and
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 7. Describe Proposed or Complete work) SEE RULE 1103. Well spudded May 6 casing at 374' and Plug down 6:45 P.M. Tested 11-3/4"GD c tested 11-3/4"GD c	change plans Change plans Change plans Change plans Casing test and cement Job Z Other Change plans Commented with 400 sacks regular cement by the plans of the surface assing up to 600f for 30 minutes and tested OX. Casing to 600f and casing shut off tested OX. Casing to 600f and casing shut off tested OX. Casing to 600f and casing shut off tested OX. Casing to 600f and casing shut off tested OX.	ding estimated date of starting any proposed. 2.20f Armco SW SJ R-3 pump and plug process. 2. WOC 24 hours. Drilled plug and

CONDITIONS OF APPROVAL, IT ANY: