

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 E. Benson Rd., Aztec, NM 87410

WELL APT NO.
30 025 22315

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
Tenneco Fee

1. Type of Well:
OIL GAS OTHER

8. Well No.
1

2. Name of Operator
Marks and Garner Production, Ltd. Co.

9. Pool name or Wellcat
Morton Permo Penn North

3. Address of Operator
P O Box 70 Lovington NM 88260

4. Well Location
Unit Letter J- 1980 Feet From The South Line and 1980 Feet From The East Line
Section 31 Township 14-S Range 35-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, CR, etc.)
4057GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| | OTHER: <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @ 10350' W/ 25 sacks cement on top(25 sacks) - TAG
Load hole W/ gel
Spot 25 sacks @ 7445' --wait 24 hrs & tag
Shoot 5 1/2" casing at free point (appx 6000')
Spot 50 sacks in & out of stub--wait 24 hrs & tag
Spot 50 sacks @ 4550'---wait 24 hrs & tag
Spot 50 sacks @ 1910'--wait 24 hrs & tag
Shoot 8-5/8" casing @ free point (appx 1000')
Spot 50 sacks in & out of stub--wait 24 hrs & tag
Spot 60 sacks @ 417' ---wait 24 hrs & tag
Set dry hole marker W/ 10 sacks @ surface

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PROPOSED OPERATIONS FOR THE CHANG TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James H. Buddy Garner TITLE Partner DATE 5-9-01

TYPE OR PRINT NAME James H. Buddy Garner TELEPHONE NO. 396-5311

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

db