

NO. OF COPIES RECEIVED
DISTRIBUTION
SANTA FE
FILE
U.S.G.S.
LAND OFFICE
OPERATOR

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

State Indicate Type of Lease
Lease <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
Lease No. L-197 & E-7934

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG WELLS IN A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Well <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Amerada Petroleum Corporation	8. Farm or Lease Name State WR "A" Com
3. Address of Operator P. O. Box 668, Hobbs, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER E 2080' FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 35 TOWNSHIP 12-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat West Ranger Lake
15. Elevation (Show whether DF, RT, GR, etc.) 4156' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spotted 50 sx cement plug fr. 12,844' to 12,974' in Devonian, 170 sx cement over Ranger Lake 10,090' to 10,400', 25 sx cement over Abo 7700' to 7778', 25 sx cement over Glorietta from 5540' to 5618', 25 sx cement in and out of 8-5/8" csg. from 4182' to 4260'. Shot 8-5/8" csg. off at 2200' pulled to 1770', csg. stuck. Shot off at 1350'. Pulled a total of 56 jts. for 1765'. Spot 25 sx cement from 2190' to 2230'. Spotted 25 sx cement in and out 13-3/8" csg. from 370' to 400'. Spot 10 sx cement in top of 13-3/8" csg. 0' to 10' w/4" x 6' dry hole marker.
Well P & A 3-29-69

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Bo Webb</i></u>	TITLE <u>Dist. Supt.</u>	DATE <u>April 5, 1969</u>
APPROVED BY <u><i>John W. Ramsey</i></u>	TITLE <u>Geologist</u>	DATE <u>SEP 8 1969</u>
CONDITION OF APPROVAL, IF ANY:		