

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

L CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG-5095	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator The Superior Oil Company		8. Farm or Lease Name State "D"
3. Address of Operator 9 Greenway Plaza - Suite 2700 - Houston, TX 77046		9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> 1980 FEET FROM THE <u>North</u> LINE AND 1980 FEET FROM <u>East</u> THE LINE, SECTION <u>4</u> TOWNSHIP <u>14-S</u> RANGE <u>34-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Cerca-Lower Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 10-22-85 MIRU DA-S Plugging Unit.
- 10-23-85 POH w/2-3/8 tbg & pkr, RIH w/CIBP, set @ 9600'.
- 10-24-85 Spot 25x Class C Neat on top CIBP (230'), displ hole w/230 bbls 10# mud, POH w/tbg.
- 10-25-85 Cut 5-1/2 csg @ 4690, LD 140 jts.
- 10-26-85 RIH w/2-3/8 tbg to 6595, circ hole w/10# mud, pump 25x Class C (250'), LD 58 jts tbg to 4740, pump cmt plug w/90x Class C (290') across top of 5-1/2 csg stub - pull tbg to 2740.
- 10-27-85 Tag cmt @ 4410, cut off 8-5/8 csg @ 990'.
- 10-28-85 LD 34 jts csg, RIH w/tbg to 1040; circ 10# mud, pump cmt plug @ 1040 w/87x Class C Neat, tag plug @ 855', pull tbg to 450', pump cmt plug w/87x Class C.

SEE REVERSE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Nancy Lewis</u>	TITLE <u>MOBIL PRODUCING TX &amp; N.M. INC AS AGENT FOR THE SUPERIOR OIL COMPANY</u>	DATE <u>11-6-85</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>AUG 31 1987</u>
CONDITIONS OF APPROVAL, IF ANY:		

10-29-85 Tag plug @ 301', run 1 jt tbg to 20'; pump 10x Class C Neat, POH, weld  
on P&A marker, RD & MO DA-S Plugging Unit. Well P&A'd.

RECEIVED  
NOV 8 - 1985  
O.C.D.  
HOBBS OFFICE