

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-22633
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other : Dry Hole		5. Indicate Type of Lease FEDERAL STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator SAHARA OPERATING COMPANY		6. State Oil & Gas Lease No. V-6626
3. Address of Operator P.O. BOX 4130, Midland, TX 79704		7. Lease Name or Unit Agreement Name: Adam State
4. Well Location Unit Letter <u>P</u> : <u>660</u> feet from the <u>SOUTH</u> line and <u>660</u> feet from the <u>East</u> line Section <u>20</u> Township <u>12</u> Range <u>33-E</u> NMPM County <u>Lea</u>		7. Well No. I
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4290' GL		9. Pool name or Wildcat Wildcat

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: Abandon Reentry ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

6-26-2002 Dug out wellhead, removed old dry hole marker, welded on wellhead.
6-27-2002 MIRU PU. NU BOP. PU 11" bit & drilled surface plug. TIH and tagged shoe plug for surface csg @ 215' (surface csg set @ 290'). Went to circulate and csg started leaking.
6-28/2002 Dug out casing with backhoe. Casing not in good enough shape to continue operations. POH & LD collars. ND BOP, cut off wellhead, set 10 sx cmt plug in surface casing, installed dry hole marker, filled cellar, cleaned location. FINAL REPORT. JOB TO REENTER WELL ABANDONED.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE 7-1-02

Type or print name Robert McAlpine Telephone No. 915-697-0967
(This space for State use)

APPROVED BY [Signature] TITLE ARY W WINK DATE JAN 15 2003
Conditions of approval, if any OC FIELD REPRESENTATIVE II/STAFF MANAGER