DISTRIBUTION					Form C+103 Supersedes Old		
SANTA FE	N MEXICO OIL	CONSE	RVATION COMMISSIC		C-102 and C-103 Effective 1-1-65		
FILE	•			ែ	a. inaicate Type of Lesse		
LAND OFFICE					State X	fee 🔲	
OPERATOR				į.	5. State Cti & Gas Lease N	.e.	
			····		L 520		
SUNDRY NOTICES AND REPORTS ON WELLS  GEO NOT USE THIS YORN FOR PROPOSAUS TO DRILL ON TO DEEPEN OF PLUC SACE TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT " IFORM CALOID FOR SUCH PROPOSALS."							
OIL CAS WELL	CTHER- SWD				7, Unit Agreement Nume		
Coastal Oil and Gas Corporation					State "22"		
C. Address of Operator					S. Well No.		
P. O. Box 235, Nidland, Texas 79702					1 SWD		
UNIT LITTER I 660 FEET FROM THE EAST LINE AND 1980 FEET FROM					Tulk (Penn.)		
THE South LINE, SECTION 22 TOWNSHIP 14-S BANCE 32-E NUPN							
15. Elevation (Show whether DF, RT, GR, etc.)					12. County	HHH:	
4298.3' GR					Lea	.1111111	
Check Ap	• •	cate N	Sature of Notice, Report		er Data REPORT OF:		
	PLUG AMD ABANDS	~. <del> </del>	REMEDIAL WORK	· ¬	ALTERING CASIN		
PENFORM PEMEDIAL WORK	PLUG ABS ABARD.	· L	COMMENCE CRILLING DPNS.		PLUE AND ASAND	=	
PULL DR ALTER CASING	CHANGE PLANS	X	CASING TEST AND CEMENT JOB			_	
t			OTHER	·			
CTHER		<u> </u>					
17. Describe Proposed of Completed Oper	ations (Clearly state all pertu	nent det	ails, and give pertinent dates, i	ncluding e	stimated date of starting a	ny proposed	
Well previously plug		via v	erbal permission (se	e c <b>-1</b> 0	3 dated 10-22-84)	٠.	
<ul> <li>2 &amp; A proposed as fo</li> <li>1. Cut off 5½" casing a</li> </ul>	llows: at 4100° amd POH wit	th sai	me.				
2. Pick up workstring.	GIH to 50' below o	casin	g stub and spot 50 s	ack pl	ug (this represer	nts	
approximately 195' o	f fill). POH with	work	string.	551 00	d 2 holos at 450!	ı	
3. Perforate 8 5/8" cas 4. GIH with workstring	ing with 4 holes at	: 255) r. T.	go and 4 hores at is	n plac	e. circulate hole	•	
with 9.5 PPG mud-lad	len fluid. Pick up	and	set retainer at 2450	' (100	' above perfs) an	nd	
squeeze 100 sacks be	elow retainer. This	s vol	ume represents 100'	of ann	ular fillup behin	ıd	
8 5/8" casing and 10	of fill below re	etain	er to perfs, plus l etainer. GIH to 145	00% ex	cess. ueeze below retai	iner	
with 100 sacks. POH	H with workstring.						
6. Pick up retainer and	GIH. Set retainer	r at	350' and sqeeze belo	w with	100 sacks. POH		
with workstring. 7. Cut off 8 5/8" casir	ng 5-10' below groun	nd le	vel. Spot cement fr	om 100	' to surface.		
Install P&A marker a	and clean location.						
		- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1		0F) 24			
is, I hereby certify that the information	above is true and complete to	the best	of my knowledge and belief.	<u></u>			
12, 1 nerecy (Filly mer on 1	,/						
- Tolly & med	<u>tt</u>	, P	etroleum Engineer		12-26-84		
ORIGINAL SIGNED BY	FRRY SEXTON				115 J. L.	15.34	
ORIGINAL SIGNAL SU	PERVISOR	1 LL					