

10. Spot 40 sks cmt plug @ top of salt @ 1970'.
11. Spot 40 sks cmt plug across 13-3/8# csg shoe @ 408'.
12. Spot 10 sks cmt @ surface install regulation dry hole marker clean & level location.