

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
 Revised 10-1-73

USE THIS SPACE FOR RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
 State ☒ Fee ☐

5. State Oil & Gas Lease No.
 OG-5217

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

6. Name of Operator
 The Superior Oil Company

7. Unit Agreement Name

8. Farm or Lease Name
 State "L"

9. Well No.
 1

10. Field and Pool, or Wildcat
 Cerca (Wolf)

11. Location of Well
 UNIT LETTER P 510 FEET FROM THE south LINE AND 660 FEET FROM
 THE east LINE, SECTION 33 TOWNSHIP 13S RANGE 34E NMPM.

12. County
 Lea

15. Elevation (Show whether DF, RT, GR, etc.)
 4136 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>
		Add perfs in Upper Wolf.	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-10-82 MI RU Carr WO rig.
 8-11-82 Perfed 9597' - 9604' w/4" gun w/2 JSPF (total 16 holes). Spotted 1000 gals
 MOD-202 acid, flushed w/KCl wtr.
 8-12-82 Swabbed.
 8-13-82 Swabbed, rec wtr w/no trace oil. SD.
 8-14-82 Swabbed, rec wtr only. Well turned over to engineering dept. for evaluation.
 LAST REPORT.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: G. E. Tate TITLE: Production Superintendent DATE: 9-29-82

ORIGINAL SIGNED BY
 APPROVED BY: W. E. SEXTON TITLE: _____ DATE: NOV 6 1982

CONDITIONS OF APPROVAL: IF ANY

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Free <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG-5217	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator THE SUPERIOR OIL COMPANY	8. Farm or Lease Name State "L"
3. Address of Operator P. O. Box 3901, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> <u>510</u> FEET FROM THE <u>south</u> LINE AND <u>660</u> FEET FROM THE <u>east</u> LINE, SECTION <u>33</u> TOWNSHIP <u>13S</u> RANGE <u>34E</u> N.M.P.M.	10. Field and Pool, or Wildcat Cerca (Wolf)
15. Elevation (Show whether DF, RT, GR, etc.) 4136' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER <u>Add perms in Upper Wolf</u> <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe all Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.

1. RU NO unit.
2. Remove prod. equip.
3. Perf @ 9597-9604' w/2 JSPF, 0° phasing.
4. Acidize w/1000 gals acid + additives.
5. Adder acid.
6. Job test if necessary.
7. Restore production if successful.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. Tate TITLE Production Superintendent DATE 9-29-82

ORIGINAL SIGNED BY JERRY BOATMAN TITLE DATE OCT 6 1982
APPROVED BY
CONDITIONS OF APPROVAL, IF ANY: None