

DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR		

U.S. CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
K-864

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☒ GAS ☐ OTHER ☐
2. Name of Operator
The Superior Oil Company
3. Address of Operator
9 Greenway Plaza - Suite 2700 - Houston, TX 77046
4. Location of Well
UNIT LETTER J 2130 FEET FROM THE South LINE AND 1980 FEET FROM
THE East LINE, SECTION 4 TOWNSHIP 14S RANGE 34E NMPM.
10. Field and Pool, or Willcat
Corca-Lower Wolfcamp
12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐ OTHER ☐ CASING TEST AND CEMENT JOB ☐
OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. Notify NMOCD 24 hrs in advance.
2. MIRU, POH w/2-3/8 tbg.
3. Set cmt ret @ +9160 on tbg.
4. Pump +450sx Class C Neat to sqz perms. Leave 35' on top cmt ret.
5. Circ w/9.5 mud.
6. Determine free point 7" csg, cut & if above 6100', recover all free csg. (If at or below 6100', contact NMOCD for new procedure).
7. Spot +55sx Class C plug across csg stub - 50' above & 50' below.
8. Spot +55sx Class C 4450-4550.
9. Circ 9.5 mud.

(SEE REVERSE)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Nancy Lewis TITLE MOBIL PRODUCING TX. & N.M., INC.
AS AGENT FOR THE SUPERIOR OIL COMPANY DATE 8-6-85

ORIGINAL SIGNED BY EDDIE SEAY

PROVED BY EDDIE SEAY TITLE OIL & GAS INSPECTOR DATE AUG 12 1985

CONDITIONS OF APPROVAL, IF ANY:

THE COMPLETION OF THE ABOVE WORK
24 HOURS PRIOR TO COMMENCING WORK

10. Determine free point 9-5/8" csg, cut & recover.
11. Spot +115sx Class C across 9-5/8 csg, 50' above & below & 50' above & below 13-3/8 csg shoe.
12. Spot 10sx Class C 0-15+.
13. Erect P&A marker & clean location.

NOTE: Wellbore to be filled w/9.5 mud between cmt plugs.

RECEIVED
AUG 12 1985
HALL OFFICE