

DATE	
BY	
FILE	
REMARKS	
LAND OFFICE	
OPERATOR	

WATER CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-79

1a. Indicate Type of Lease
State ☒ Line ☐
b. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator THE SUPERIOR OIL COMPANY	8. Form or Lease Name STATE K
3. Address of Operator P. O. BOX 4500 THE WOODLANDS, TX 77380	9. Well No. 1
4. Location of Well UNIT LETTER D 2130 FEET FROM THE South LINE AND 1980' FEET FROM THE East LINE, SECTION 4 TOWNSHIP 14S RANGE 34E MAPAS.	10. Field and Pool, or Wildcat Cerca; Upper Penn. Wolf- camp
15. Elevation (Show whether DF, RT, GR, etc.) KB: 4154' GL: 4138'	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. Install BOP.
2. GIH w/chemical cutter and cut tbq. POH w/tbg.
3. GIH w/overshot recover remainder tbq.
4. Run gauge ring.
5. If casing collapsed, swedge out.
6. If casing leaks, squeeze it.
7. Pull well back on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. H. BOHOT TITLE Engineering Supervisor DATE 4-28-81

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

CC: COM (3), PRB, WHS, EJW, JWH, RG, CF