F.O. Box 1980, Hobbs, NM 88240

DISTRICT F.O. Drawer DD, Arlesia, NM 88210

DISTRICT III

OIL CONSERVATION DIVISION

P.O. Box 2088

| Santa | Fe. | New | Mexico | 87504-2088 |
|-------|-----|-----|--------|------------|
|-------|-----|-----|--------|------------|

| 5. Indicate Type of Lease STATE X | FFF | |
|-----------------------------------|-----|--|

| DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410 | 6. State Oil & Gas Lease No. K-6272 & B-399-35 | | |
|---------------------------------------------------------------------------------------------------------|-------------------------------------------------|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG! | K TO A 7. Lease Name or Unit Agreement Name | | |
| DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | | |
| 1. Type of Well: OL GAS WELL X WELL OTHER | State 19 Comm. | | |
| 2. Name of Operator | 8. Well Na | | |
| Petroleum Production Management, Inc. | 11 | | |
| 3. Adoress of Operator | 9. Pool name or Wildcar | | |
| Suite 200/Sutton Place Bldg. Wichita, Kansas | 6720 Undesig Toolf Camp | | |
| 4. Well Location | <i>y</i> 0 | | |
| Unit Letter I : 660 Feet From The East Line | and 1980 Feet From The South Line | | |
| Section 19 Township 13-S Range | 33-E NMPM Lea County | | |
| 10. Elevation (Show whether DF, RKB, KT 4279.3' KB, 4278.3' D | | | |
| 11. Check Appropriate Box to Indicate Nature of | Notice, Report, or Other Data | | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: | | |
| ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA | AL WORK ALTERING CASING | | |
| EMPORARII Y ARANDON CHANGE PLANS COMMEN | ICE DRILLING OPNS. PLUG AND ABANDONMENT | | |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

X

- 1. Pull out of hole with rods and tubing.
- 2. Perforate Wolfcamp formation 9370'-9374'.

CHANGE PLANS

Set retrievable bridge plug in 5 1/2" casing at 9420' and packer at 9280'. 3.

OTHER:_

CASING TEST AND CEMENT JOB L

4. Swab and test.

OTHER Plug back and Perforate in Wolfcamp

- 5. Acidize as necessary.
- 6. Perforate interval 9220'-9224'.
- 7. Swab and test.
- Acidize as necessary.

| <i>\(\frac{1}{2}\)</i> | | , | 1 | |
|-------------------------------------------------|--------------------------------------------------------|--------------------------------------------|-----------------|--------------------|
| I hereby certify that the information Signature | cide above is true and complete to the best of my know | iedge med bedief. ராம District Engineer | DATE 8-23 | -90 |
| TYPE OR PRINT NAME | W.M. Groesbeck | | телечноче но 67 | 5-2478 |
| (Thus apace for State Use) | Orig. Signed by Paul Kautz | | : | % 4 ± ₹1 2 + |
| AFTROVED BY | Geologist | TITLE | DATE | |

TEMPORARILY ABANDON

PULL OR ALTER CASING