

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K6272 & B399-25	
7. Unit Agreement Name	
8. Farm or Lease Name	
State "19"	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
North Baum, Upper Penn	
12. County	
Lea	

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center">(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Delaware-Apache Corporation	State "19"
3. Address of Operator	9. Well No.
1720 Wilco Bldg. Midland, Texas 79701	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>I</u> <u>660</u> FEET FROM THE <u>East</u> LINE AND <u>1980</u> FEET FROM	North Baum, Upper Penn
THE <u>South</u> LINE, SECTION <u>19</u> TOWNSHIP <u>13S</u> RANGE <u>33E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
Gr 4267.3'	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Start the following work approximately 1-25-71

Pull 2-3/8" tubing, perforate Bough "A" & "B" zones from approximately 9558'-9709'
Set Bridge Plug above Bough "C" @ 9730'. Acidize with 5000 gals acid. Run tubing, swab test. Produce Bough "A" & "B" until necessary to pump, then produce A, B & C commingled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Bonnie Husband</u>	TITLE <u>Production Clerk</u>	DATE <u>1-18-71</u>
APPROVED BY <u>Joe Ramsey</u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>JAN 20 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JAN 10 1971

OIL CONSERVATION COMM.
HISSE, L. H.