

1. COPIES RECEIVED
 2. DISTRIBUTION
 3. NAME
 4. ADDRESS
 5. PHONE
 6. FIELD OFFICE
 7. MAILING ADDRESS

NEW MEXICO OIL CONSERVATION COMMISSION

Form O-103
 Supersedes Old
 O-102 and O-103
 Effective 1-1-66

8a. Indicate Type of Lease
 Date ☒ Fee ☐
 8. State Oil & Gas Lease No.
 1-44

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR PLUG BACK TO A DIFFERENT RESERVOIR.

1. Well No. ☐ 2. Well No. ☐ OTHER: Dry Hole

3. Name of Operator
 Conoco States Gas Producing Company

4. Address of Operator
 Box 293, Midland, Texas 79701

7. Unit Agreement Name
 - - -
 8. Part of Lease Name
 State "26"
 9. Well No.
 2

10. Location of Well
 3 660 FEET FROM THE north 1980
 UNIT LETTER EAST LINE, SECTION 26 TOWNSHIP 14S RANGE 32E N.M.P.M.
 11. Elevation (Show whether DP, RT, GR, etc.)
 4285.5'

10. Name and No. of Well
 Undesignated
 11. County
 Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

REPAIR & REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
REPAIR OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT LOG ☐	

12. Nature of Operation or Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting, any proposed work) SEE RULE 103.

Well No. 2 was spudded 9-29-66; set 13-5/8" surface casing at 3952' and set 8-5/8" productive casing at 4035'. Well was drilled to TD 10,102'. Ran Dual Induction Laterolog, Sidewall Neutron Porosity and Microlog logs - results showed well to be dry and non-productive.

Well will be plugged and abandoned as follows:

1. Set 50-sack cement plug at 10,102'.
2. Set 25-sack cement plug at 9,000'.
3. Set 25-sack cement plug at top of 8-5/8" stub.
4. Weld steel plate on top of 13-5/8" and install dry hole marker.
5. Temporarily abandon until 8-5/8" string of casing can be recovered.

25 x 25 Top Ab.
 25 " in + ext of 8 5/8" stub
 25 " in + ext of 8 5/8" stub

25 x 25 Top 20 ft
 25 " in + ext of 13 5/8" stub
 10 " Surface

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

13. Signature of Operator
 14. Signature of Production Manager
 15. Signature of Inspector

16. Date
 February 27, 1969